

PRO DISPOSAL USA (BARNWELL RESOURCES) CLASS 2 LANDFILL : P1TJ-QJAP-426



Solid Waste - Class 2 Landfill : SW_CLS2_LF

Solid Waste - Class 2 Landfill	
Facility	
Facility Name PRO DISPOSAL USA (BARNWELL RESOURCES) CLASS 2 LANDFILL	
Date of Inspection	6/15/2026
Time of Inspection	10:38 AM
County	Beaufort
Permit #	072410-1201
Inspection Processing	
Reason for Inspection	Routine
Weather Conditions	Sunny
Temperature	80s
Rainfall in past week	1-1.5
Weather Condition Description Heavy rainfall on day prior to inspection.	
Last Inspection	05/26/2026
Inspection Detail	
1. Attendant Present	Yes
2. Required signs posted	Yes
3. Inspection of all incoming loads conducted	Yes
4. Unauthorized waste training conducted and documented	Not Applicable
5. No unauthorized waste present	Yes
6. Access controlled	Yes
7. Adequate entrance all-weather roads	Yes
8. Adequate internal all-weather haul roads	Yes

PRO DISPOSAL USA (BARNWELL RESOURCES) CLASS 2 LANDFILL : P1TJ-QJAP-426



Solid Waste - Class 2 Landfill : SW_CLS2_LF

Inspection Detail

9. Frequency of cover meets regulatory/ permit requirements No

Comments:

A little cover has been added since last inspection, but 30 day full cover requirement has not been met (R.61-107.19 part IV.C.7)



Photo Taken: 6/15/2026 10:40:00 AM
GPS Latitude: 32.471738
GPS Longitude: -80.649452
GPS Altitude: 21.290000 meters
GPS Orientation: 1 degrees

10. > Six inches of soil (short-term cover) meets regulatory/permit requirements Yes

11. Approved Alternate Monthly Cover (AMC) used Not Applicable

12. > Six inches of soil (long-term and/or intermediate cover) meets regulatory/permit requirements Yes

13. Adequate soil quantity available for cover Yes

14. Working face slope does not exceed 3:1 Yes

PRO DISPOSAL USA (BARNWELL RESOURCES) CLASS 2 LANDFILL : P1TJ-QJAP-426



Solid Waste - Class 2 Landfill : SW_CLS2_LF

Inspection Detail

15. Waste spread in uniform layers and compacted to smallest practical volume

Yes

Comments:

Some of the working face needs better compaction. Get this done once compactor is back online.



Photo Taken: 6/15/2026 10:30:00 AM
GPS Latitude: 32.473122
GPS Longitude: -80.649222
GPS Altitude: 8.860000 meters
GPS Orientation: 1 degrees

16. Working face as small as can efficiently and safely be managed

No

Comments:

Working face too large, get this covered up before next inspection.



Photo Taken: 6/15/2026 10:29:00 AM
GPS Latitude: 32.473530
GPS Longitude: -80.647744
GPS Altitude: 9.610000 meters
GPS Orientation: 1 degrees

PRO DISPOSAL USA (BARNWELL RESOURCES) CLASS 2 LANDFILL : P1TJ-QJAP-426



Solid Waste - Class 2 Landfill : SW_CLS2_LF

Inspection Detail



Jun 15, 2026 at 10:29:33 AM
239-299 Middle Rd
Beaufort SC 29906
United States

Photo Taken: 6/15/2026 10:29:00 AM
GPS Latitude: 32.473530
GPS Longitude: -80.647744
GPS Altitude: 9.610000 meters
GPS Orientation: 1 degrees



Jun 15, 2026 at 10:30:18 AM
Beaufort SC 29907
United States
Lady's Island

Photo Taken: 6/15/2026 10:30:00 AM
GPS Latitude: 32.473122
GPS Longitude: -80.649222
GPS Altitude: 8.860000 meters
GPS Orientation: 1 degrees



Jun 15, 2026 at 10:33:38 AM
Beaufort SC 29907
United States
Lady's Island

Photo Taken: 6/15/2026 10:33:00 AM
GPS Latitude: 32.470852
GPS Longitude: -80.648377
GPS Altitude: 21.290000 meters
GPS Orientation: 1 degrees

PRO DISPOSAL USA (BARNWELL RESOURCES) CLASS 2 LANDFILL : P1TJ-QJAP-426



Solid Waste - Class 2 Landfill : SW_CLS2_LF

Inspection Detail

17. Asbestos containing material adequately handled

Yes

Comments:

One load of asbestos accepted since last inspection, was immediately covered and logged.




Photo Taken: 6/15/2026 10:51:00 AM
GPS Latitude: 32.474822
GPS Longitude: -80.649252
GPS Altitude: 1.870000 meters
GPS Orientation: 1 degrees

18. Dead animals adequately handled

Not Applicable

19. All required equipment operational

No

Comments:

Compactor and backup are down, operator stated one should be back up in a few days.



Photo Taken: 6/15/2026 10:29:00 AM
GPS Latitude: 32.473347
GPS Longitude: -80.648688
GPS Altitude: 11.840000 meters
GPS Orientation: 1 degrees

20. Access to fire equipment and fire fighting services

Yes

21. Disposal area graded to a minimum 1% slope

Yes

PRO DISPOSAL USA (BARNWELL RESOURCES) CLASS 2 LANDFILL : P1TJ-QJAP-426



Solid Waste - Class 2 Landfill : SW_CLS2_LF

Inspection Detail

22. Adequate condition of ditches/swales Yes

23. Adequate condition of berms/terraces/downchutes Yes

Comments:

Minor washout from recent rain event. Berm being constructed at landfill peak along eastern slope to prevent future washouts.



Photo Taken: 6/15/2026 10:36:00 AM
GPS Latitude: 32.471077
GPS Longitude: -80.648613
GPS Altitude: 31.200000 meters
GPS Orientation: 1 degrees



Photo Taken: 6/15/2026 10:36:00 AM
GPS Latitude: 32.471077
GPS Longitude: -80.648613
GPS Altitude: 31.200000 meters
GPS Orientation: 1 degrees

24. Adequate condition of sedimentation ponds Yes

25. Control of Dust Yes

26. Control of Litter Yes

PRO DISPOSAL USA (BARNWELL RESOURCES) CLASS 2 LANDFILL : P1TJ-QJAP-426



Solid Waste - Class 2 Landfill : SW_CLS2_LF

Inspection Detail	
27. Control of Odors	Yes
<i>Comments:</i> Very slight H2S odor along Middle Rd.	
28. Control of Vectors	Yes
29. Control of Fires/Open Burning	Yes
30. Scales installed and functioning properly	Yes
31. Scales calibrated adequately	Not Inspected
32. Monitoring well pads are free of sediment buildup and standing water	Not Inspected
33. Monitoring wells pads are free of cracks	Not Inspected
34. Monitoring wells are labeled	Not Inspected
35. Monitoring wells are locked	Not Inspected
36. Operating in accordance with approved plans	Yes
37. Approved engineering drawings available	Not Inspected
38. Approved operational plan available	Not Inspected
39. Approved stabilization/landscaping plan available	Not Inspected
40. Approved contingency plan available	Not Inspected
41. Approved groundwater monitoring plan available	Not Inspected
42. Approved closure/post-closure plan available	Not Inspected
43. Required records maintained	Not Inspected
Corrective Action	
1. Corrective Action Due Date	7/16/2026
<i>Comments:</i> Once compactor is back up, get all waste compacted and covered to meet 30 day cover requirement. Maintain as small a working face as can be safely and efficiently managed.	

PRO DISPOSAL USA (BARNWELL RESOURCES) CLASS 2 LANDFILL : P1TJ-QJAP-426



Solid Waste - Class 2 Landfill : SW_CLS2_LF

Additional Comments

Record any additional information regarding the current activities at the site that has not already been captured in the previous questions

SCS has collected samples and flown drone to look for gas hotspots for the proposed gas collection system. Facility is still documenting daily odor monitoring (photos attached). Eastern slope has had test bores for thickness, areas not at 2' of cover will be capped.




Photo Taken: 6/15/2026 10:25:00 AM
GPS Latitude: 32.474708
GPS Longitude: -80.649194
GPS Altitude: 2.380000 meters
GPS Orientation: 1 degrees




Photo Taken: 6/15/2026 10:25:00 AM
GPS Latitude: 32.474708
GPS Longitude: -80.649194
GPS Altitude: 2.380000 meters
GPS Orientation: 1 degrees

PRO DISPOSAL USA (BARNWELL RESOURCES) CLASS 2 LANDFILL : P1TJ-QJAP-426



Solid Waste - Class 2 Landfill : SW_CLS2_LF

Additional Comments




Photo Taken: 6/15/2026 10:25:00 AM
GPS Latitude: 32.474708
GPS Longitude: -80.649194
GPS Altitude: 2.380000 meters
GPS Orientation: 1 degrees

Signature

Name of those present during inspection

Maci Dean, Colin Scherer

1. Facility Representative

1a. Facility Representative Name

Colin Scherer

2. SCDES Inspector

2a. SCDES Inspector Name

Colin T. Scherer