SIGNIFICANT HAZARD INSPECTION REPORT

Date _ May 24, 2001
Dam Mirror Lake Dam #2 , D-0220, Chester Co
Representatives of SCDHEC Present:Joe Faris, Jr
Representatives of Owner Present: None
Others Present:
List of noted deficiencies or items requiring correction/checking:
Slopes are badly overgrown making a comprehensive inspection difficult. Trees
smaller than 6" in diameter and all brush must be removed.
List of previously noted items still uncorrected and dates previously noted:
same as above
Emergency Action Plan Updated Yes No
Signature of Person Completing Form

SIGNIFICANT HAZARD INSPECTION REPORT

Date <u>May 24, 2001</u>
DamMirror Lake Dam #1 , D-0219, Chester Co
Representatives of SCDHEC Present:Joe Faris, Jr.
Representatives of Owner Present: None
Others Present:
List of noted deficiencies or items requiring correction/checking:
Slopes are badly overgrown making a comprehensive inspection difficult. Trees
smaller than 6" in diameter and all brush must be removed.
List of previously noted items still uncorrected and dates previously noted:
same as above
Emergency Action Plan Updated Yes No
Signature of Person Completing Form

Date
Dam Loblolly Timberlands Dam #2, D-0218
Representatives of SCDHEC Present: <u>Joe Faris, District Engineer</u>
Representatives of Owner Present: None
Others Present:
List of noted deficiencies or items requiring correction/checking:
Slopes are heavily overgrown, all vegetation less than 6" in diameter should be
removed
List of previously noted items still uncorrected and dates previously noted: Same
Emergency Action Plan Updated YesNo

Date May 24, 2001
Dam Loblolly Timberlands Dam #1, D-0210
Representatives of SCDHEC Present: <u>Joe Faris, District Engineer</u>
Representatives of Owner Present: None
Others Present:
List of noted deficiencies or items requiring correction/checking:
Slopes are heavily overgrown, all vegetation less than 6" in diameter should be
removed
List of previously noted items still uncorrected and dates previously noted:
Same
Emergency Action Plan Updated YesNo
Signature of Person Completing Form

Date : 12/2/08	
Dam: D-0227	
Representatives of SCOHEC Present: Greg Harrington	
Others Present:	
Listed of noted deficiencies or items requiring correction/checking: On December 2, 2008, I conducted a re-inspection of the above referenced dam. Overall the dam appears structurally sound, shrubs and trees should be removed from the slopes of the dam. Trees with 6" diameter or more should not be removed.	
List of previously noted items still uncorrected and dates previously noted:	
Emergency Action Plan Updated: X -Yes No	
	Greg Harrington DHEC Person Completing Form
DHEC 2604 (10/08)	

Date: 12/2/08	
B 0222	
Dam: D-0223	
Representatives of SCDHEC Present: Greg Harrington	
Note that the birds and the same of the sa	
Others Present:	
Listed of noted deficiencies or items requiring correction/checking:	
On December 2, 2008, I conducted a re-inspection of the above	
referenced dam. Overall the dam appears structurally sound,	
shrubs and trees should be removed from the slopes of the dam. Trees with 6" diameter or more should not be removed.	
Trees with o diameter of more should not be removed.	
List of previously noted items still uncorrected and dates previously noted:	
Emergency Action Plan Updated: X -Yes No	
Emergency Action Claim operation. A 166 No.	
	Greg Harrington
	OHEC Person Completing Form
DHEC 2604 (10/08)	

Date: 11/6/09	
Dam: D 0214	
The state of Control C	
Representatives of SCDHEC Present: Greg Harrington	
Others Present: Ms. Jackie Hauermann with the SC DNR	
Listed of noted deficiencies or items requiring correction/checking: On November 6, 2009 I conducted a re-inspection of the above	
referenced dam with Ms. Jackie Hauermann with the SC DNR.	
Shrubs should be removed from both the upstream and	
downstream slopes of the dam. Trees with 6" diameter or	
more should not be removed. The upstream and downstream slopes need to be mowed.	
stopes need to be mowed.	
List of previously noted items still uncorrected and dates previously noted:	
Emergency Action Plan Updated: X -Yes No	
	Greg Harrington
	DHEC Person Completing Form
8	li .
DUCD 0007 (40 (00)	
DHEC 2604 (10/08)	



GP 7 -

Preliminary Inspection Report for South Carolina Regulated Dams and Impoundment Structures Regulations R.72-1 through R.72-9

PROMOTE PROTECT PROSPER	
Section I (Owner's Information)	
A. Dam Number: D 6217 & Hazard Class 62-	B. Name of Dam: Lave Oliphant Dan
C. Inspection Date (12, 17, 120 14) & Time:	D. Date of Last Inspection: (/_ /)
E. Location-County/City: Che St(V)	F. EQC Regional Office: Lan (astru-
G. Inspector's Name: KVICK JUNES - Reg	word Engineer
H. Owner's Name: SC Department of	
Contact Person (if different from above):	
J. Dam Owner's or Contact Person's Phone Numbers:	Home ()
	Office ()
	Other ()
K. Dam Owner's or Contact Person's mailing address:	
Address 1 PO BOX 167	
Address 2 (optional)	
City (blumbla, State)	SC Zip Code 29202
Section II (Dam Condition)	
General Condition Assessment (Select one of the follow	ving):
a) Satisfactory b) Fair c) Poor	d) Unsatisfactory e) Not Rated
Section III (Dam Inspection Checklist)	
A. Dam Crest i. Vegetation (grass, trees weeds)?	to see more regetation
ii. Animal activity observed? ASMING being	done.
iii. Any obvious alteration or repairs made? MOY (
iv. Erosion noticed on crest? MS USUA (15515) STORM WE EV. v. Any visible settlement, misalignment or cracks? M PAVE TOV VIC.	ed move grass or vegetation usion constant usage, dam located
DHEC 2604 (Rev 11/2011)	

F. Auxiliary (Emergency) Spillway continued v. If applicable, any observed exposure of rebar reinforcement?
vi. If applicable, any visible leakage below concrete spillway?
H. Downstream/Hazard Class Issues i. Any noticeable changes immediately downstream of the dam that affects the hazard classification?
i. Emergency Action Plan (EAP) i. Emergency Action Plan provided by owner? Provided for an unclude wedled ii. Does EAP contains emergency alert notification plan? If so, when was it last updated?
iii. Does EAP contain specific actions to take if the dam has failed or is near failure?
Section IV (Conclusions)
General comments and recommendations:
The debris within the affect pipe, should be removed as This could hinder water flow.
* tree removal from the downstream should be addressed
be monitored and ve-stublized
have been included to be updated and sent back tomy
in a timely manner.

<u>Preliminary Dam Inspection Disclaimer:</u>

The information contained in the preliminary inspection report is intended as an aid to identify those dams that require maintenance and/or repair actions to reduce their danger to human life or property only. It is not intended as professional engineering or consulting advice for conditions or situations present at individual dams. It is not a substitute for a detailed inspection, nor does it replace the need for services provided by registered professional engineers. If your dam is experiencing an unusual situation consult with engineering professionals to find an appropriate remedy. Preliminary inspections conducted by South Carolina Department of Health and Environmental Control (the Department) are provided "AS IS" and "as available", without warranties of any kind, either express or implied. Preliminary inspections consist only of a visual but technical examination of the dam and its appurtenant works. All findings are based solely on visual observations of the inspector at the time of the inspection. Common law holds that the storage of water is a hazardous activity and the Department does not assume any responsibility or risk for your actions or inactions. Dam owners are responsible for the safe operations and maintenance of their impoundment structures.

DHEC 2604 (Rev 11/2011)



W. Marshall Taylor Jr., Acting Director

Promoting and protecting the health of the public and the environment

February 23, 2014

To:

SC Department of Parks Recreation & Tourism

1205 Pendleton Street Columbia, SC 29201

FROM:

Kristen Jones

2475 DHEC RD.

LANCASTER, SC 29720

RE: Re-inspection of Dam D-0206, Chester State Park Dam, Chester County

To Whom It May Concern:

On December 16, 2014, I conducted a re-inspection of the above referenced dam. I have enclosed a copy of my inspection report with correlating pictures taken from this dam.

Overall, the dam appears to be in POOR condition. Poor conditions are used when uncertainties exist as to critical analysis parameters, which identify a potential dam safety deficiency. Further investigations and studies are necessary. Please, review the contents of my inspection closely and make necessary adjustments listed in Section IV (Conclusions), for general comments and recommendations.

During my inspection, I found the downstream slope to have many issues. I feel that if not properly addressed the problems outlined below, will hinder the stability of the Dam. <u>Please address these concerns</u> with corrective measures, in writing by Friday March 20, 2015.

Concerns:

- the massive amount of erosion on the downstream slope,
- Vegetation along both slopes should be better maintained, shrubs on the upstream should be removed.
- size of trees located on the downstream slope

If the above items are not sufficiently addressed by the time allowed this matter may be turned over to enforcement for additional actions.

A copy of the Emergency Notification Plan is enclosed, please update and send back to our office. Should the dam experience difficulty, the agencies listed on the Plan should be contacted and may be able to provide assistance.

Provisions in the S.C. Dams and Reservoirs Safety Act require the owner to notify us within 30 days after transferring title or control of his dam to someone else. The notification must include the name and address of the new owner. I am enclosing a blank form for your use in notifying us should control of your dam be transferred.

You will be notified when the next re-inspection of this dam is scheduled, by the Department. Items listed on inspection report should be addressed before the next inspection. If you have any questions or comments, please call me at (803) 285-7461 or email me at joneskl@dhec.sc.gov.

Sincerely,

Kristen Jones

Regional Engineer

Enclosures:

Inspection Report, Site Pictures, Surveillance, Emergency Notification and Action Plan, Notification Form for

Ownership Change

Cc:

File Room

<u>occuon</u>	III (Dam Inspection Checklist) continued
B. Upstre	
	ation (grass, trees weeds)? a lot at vegetutan on the upstrem
	al activity observed?
iii. Any o	bvious alterations or repairs made? WD
iv. Erosio	n observed on upstream slope?
v. Settlen	nent or cracks visible in slope?
	tream Slope
and St	tion (grass, trees weeds)? Thes have grown since last inspector
	activity observed? No
iii. Any ob	ovious alterations or repairs made? (NO
iv. Erosior	observed on down stream slope? Sime slowering observed
v. Settlem	ent or cracks visible in slope?
vi. Toe dra	nins flowing?
vii. Any se	epage observed? If so, describe location, None
flow rate, a	and any turbidity or color within the flow:
	and any turbidity of color within the now:
) Primary	
D. Primary S i. Any visib	Spillway
D. Primary i i. Any visib	
i. Any visib	Spillway
i. Any visib	Spillway le deterioration of structure? an obvious need to repair or replace trash rack?
ii. Is there a	Spillway le deterioration of structure? an obvious need to repair or replace trash rack?
ii. Is there a iii. Any noti	Spillway le deterioration of structure? an obvious need to repair or replace trash rack? ceable problems with debris? at of control with amount of debris present or gate present? 483
ii. Is there a iii. Any noti	Spillway le deterioration of structure? an obvious need to repair or replace trash rack? ceable problems with debris? at of control with amount of debris present or gate present?
ii. Is there a iii. Any noti NO+ iv. Is valve E. Outlet Pip i. Any water	Spillway le deterioration of structure? an obvious need to repair or replace trash rack? ceable problems with debris? at of control with amount of debris present or gate present? 483
ii. Is there a iii. Any noti NOT iv. Is valve E. Outlet Pil i. Any water ii. Describe	Spillway le deterioration of structure? an obvious need to repair or replace trash rack? ceable problems with debris? the the vemoved however or gate present? pe rvisibly flowing or leaking outside of the discharge pipe?
ii. Is there a iii. Any noti NO+ iv. Is valve C. Outlet Pi i. Any water ii. Describe iii. Visible co	Spillway le deterioration of structure? an obvious need to repair or replace trash rack? ceable problems with debris? at at control with amount of debris present or gate present? visibly flowing or leaking outside of the discharge pipe? any deflection or damage observed to the pipe: condition of outlet channel: condition of out
ii. Is there a iii. Any noti NO+ iv. Is valve C. Outlet Pi i. Any water ii. Describe iii. Visible co	Spillway le deterioration of structure? In obvious need to repair or replace trash rack? In one ceable problems with debris? In one or gate present? In one replace trash rack? In one or gate present? In one or yes any deflection or damage observed to the pipe: In one ondition of outlet channel:
ii. Is there a iii. Any noti NO+ iv. Is valve E. Outlet Pi i. Any water ii. Describe iii. Visible co Auxiliary (Noticeable	Spillway le deterioration of structure? an obvious need to repair or replace trash rack? ceable problems with debris? and the control with amount of debris present or gate present? per visibly flowing or leaking outside of the discharge pipe? any deflection or damage observed to the pipe: condition of outlet channel: condition of outlet channel: conditions to flow?
ii. Is there a iii. Any noti NOT iv. Is valve E. Outlet Pil i. Any water ii. Describe iii. Visible co Auxiliary (Noticeable i. Animal act	Spillway le deterioration of structure? an obvious need to repair or replace trash rack? ceable problems with debris? Cutto be vemoved however out of control with amount of debris present or gate present? pe visibly flowing or leaking outside of the discharge pipe? any deflection or damage observed to the pipe: condition of outlet channel: pow Emergency) Spillway obstructions to flow?
ii. Is there a iii. Any noti NOT iv. Is valve iv. Is valve Outlet Pi i. Any water ii. Describe iii. Visible co Auxiliary (Noticeable i. Animal act i. Any notice	Spillway le deterioration of structure? an obvious need to repair or replace trash rack? ceable problems with debris? Cut the vemoved however to debrus present or gate present? or gate present? any deflection or damage observed to the pipe: condition of outlet channel: condition of outlet channel: condition of outlet channel: condition of flow?



Preliminary Inspection Report for South Carolina Regulated Dams and Impoundment Structures Regulations R.72-1 through R.72-9

Section I (Owner's Information)
A. Dam Number: DOZOG & Hazard Class CZ B. Name of Dam: Choster Stute Park
C. Inspection Date (12/19/2014) & Time: D. Date of Last Inspection: (//)
E. Location-County/City: Chester / Chester F. EQC Regional Office: Lancastru
G. Inspector's Name: Kristin Jones - Regional Engineer
H. Owner's Name: SC Department at Parks + Pac. + Poursm
I. Contact Person (if different from above):
J. Dam Owner's or Contact Person's Phone Numbers: Home 843 673 40 17
Office ()
Other () K. Dam Owner's or Contact Person's mailing address:
Address 1_ 1205 Dandleton Street
Address 2 (optional)
City Columbia , State SC zip Code 2920
Section II (Dam Condition)
General Condition Assessment (Select one of the following):
a) Satisfactory b) Fair c) Poor d) Unsatisfactory e) Not Rated
Section III (Dam Inspection Checklist)
A. Dam Crest i. Vegetation (grass, trees weeds)? Fine, milds to be cut lover
ii. Animal activity observed?non
iii. Any obvious alteration or repairs made?
iv. Erosion noticed on crest? MD
v. Any visible settlement, misalignment or cracks?
DHEC 2604 (Rev 11/2011)


F. Auxiliary (Emergency) Spillway continued v. If applicable, any observed exposure of rebar reinforcement?
vi. If applicable, any visible leakage below concrete spillway?
H. Downstream/Hazard Class Issues i. Any noticeable changes immediately downstream of the dam that affects the hazard classification?
I. Emergency Action Plan (EAP) i. Emergency Action Plan provided by owner? Vivided for Updated Information
ii. Does EAP contains emergency alert notification plan? If so, when was it last updated?
iii. Does EAP contain specific actions to take if the dam has failed or is near failure?
Section IV (Conclusions) General comments and recommendations: ** Overall dam appears to be structurally sound ** Alven a faw issues with the downstream store
- trees have grown producing massive roots which wild eventually interfer with the stubility of the dam - sloughing on the slope should be address before future issues arise
- aut any trees within 20 ft at the toe of the dom * given a poor condition because lock of maintaine on the downstream slope * A charge of auneiship form has been provided please mail back it adjuments have been made. * Please update Emergency Action Plan Include and mail back to my office with comments addressing the above usues.

Preliminary Dam Inspection Disclaimer:

The information contained in the preliminary inspection report is intended as an aid to identify those dams that require maintenance and/or repair actions to reduce their danger to human life or property only. It is not intended as professional engineering or consulting advice for conditions or situations present at individual dams. It is not a substitute for a detailed inspection, nor does it replace the need for services provided by registered professional engineers. If your dam is experiencing an unusual situation consult with engineering professionals to find an appropriate remedy. Preliminary inspections conducted by South Carolina Department of Health and Environmental Control (the Department) are provided "AS IS" and "as available", without warranties of any kind, either express or implied. Preliminary inspections consist only of a visual but technical examination of the dam and its appurtenant works. All findings are based solely on visual observations of the inspector at the time of the inspection. Common law holds that the storage of water is a hazardous activity and the Department does not assume any responsibility or risk for your actions or inactions. Dam owners are responsible for the safe operations and maintenance of their impoundment structures.

DHEC 2604 (Rev 11/2011)

D-0206 Chester State Park





C. Earl Hunter, Commissioner

Promoting and protecting the health of the public and the environment.

January 19, 2010

ROCKY CREEK WCD Mr. BRUCE ANDREWS 744B WILSON ST CHESTER, SC 29706

RE: Re-inspection of ROCKY CREEK WCD DAM NO. 6, D 0213, Chester County

Dear Mr. ANDREWS:

On November 6, 2009 I conducted a re-inspection of the above referenced dam with Ms. Jackie Hauermann with the SC DNR. Shrubs should be removed from both the upstream and downstream slopes of the dam. Trees with 6" diameter or more should not be removed. An inspection report is enclosed.

A copy of the Emergency Notification Plan is enclosed for your use. Should the dam experience difficulty, the agencies listed on the Plan can provide assistance in possibly closing down stream roads or contacting down stream property owners. These agencies should be contacted in case an emergency occurs.

Provisions in the S.C. Dams and Reservoirs Safety Act require the owner to notify us within 30 days after transferring title or control of his dam to someone else. The notification must include the name and address of the new owner. I am enclosing a blank form for your use in notifying us should control of your dams be transferred.

You will be notified when the next re-inspection of this dam is scheduled.

Sincerely

District Engineer

District Engineer

Cc: Susan Scott – File Room

Date: 11/6/09	
Dam: D 0213	
Representatives of SCDHEC Present: Greg Harrington	
Representatives of Sconec Fresent: oreginarington	
74	
Others Present: Ms. Jackie Hauermann with the SC DNR	
Listed of noted deficiencies or items requiring correction/checking:	
On November 6, 2009 I conducted a re-inspection of the above referenced dam. Shrubs should be removed from both the	-
upstream and downstream slopes of the dam. Trees with 6"	
diameter or more should not be removed	
List of previously noted items still uncorrected and dates previously noted:	
LIST OF PERFORMING THE TEST STATE WHICH FEETED BING HOLES PERFORMING HOLES.	
	-
	-
Emergency Action Plan Updated: X -Yes No	
	8
	Greg Harrington
	DHEC Person Completing Form
	DITED FELSON DUMPIERING FORM
DHEC 2604 (10/08)	



W. Marshall Taylor Jr., Acting Director Promoting and protecting the health of the public and the environment

February 23, 2014

To:

Pineview Lakes HOA

PO Box 608

Chester, SC 29706

FROM:

Kristen Jones

2475 DHEC RD.

LANCASTER, SC 29720

RE: Re-inspection of Dam D-0224, Pineview Lakes Dam 1, Chester County

To Whom It May Concern:

On December 16, 2014, I conducted a re-inspection of the above referenced dam. I have enclosed a copy of my inspection report with correlating pictures taken from this dam.

Overall, the dam appears to be in FAIR condition. This rating is assigned to dams where there is no existing safety deficiencies recognized for normal loading conditions. Please, review the contents of my inspection closely and make necessary adjustments listed in Section IV (Conclusions), for general comments and recommendations.

A copy of the Emergency Notification Plan is enclosed, please update and send back to our office. Should the dam experience difficulty, the agencies listed on the Plan should be contacted and may be able to provide assistance.

Provisions in the S.C. Dams and Reservoirs Safety Act require the owner to notify us within 30 days after transferring title or control of his dam to someone else. The notification must include the name and address of the new owner. I am enclosing a blank form for your use in notifying us should control of your dam be transferred.

You will be notified when the next reinspection of this dam is scheduled, by the Department. Items listed on inspection report should be addressed before the next inspection. If you have any questions or comments, please call me at (803) 285-7461 or email me at joneskl@dhec.sc.gov.

Sincerely

Kristen Jones

Regional Engineer

Enclosures:

Inspection Report, Site Pictures, Surveillance, Emergency Notification and Action Plan, Notification Form for

Ownership Change

Cc: File Room



Preliminary Inspection Report for South Carolina Regulated Dams and Impoundment Structures Regulations R.72-1 through R.72-9

OTE PROTECT PROSPER

Section I (Owner's Information)	
A. Dam Number: D ONY & Hazard Class C2	B. Name of Dam: PINLUICLD Lake Dam
C. Inspection Date (2/16/2014) & Time:	D. Date of Last Inspection: (//)
E. Location-County/City:	F. EQC Regional Office:
G. Inspector's Name: KYISTEN LONGS - REGIO	nal Engine V
H. Owner's Name: PINEVIEW Lake HOF	+
I. Contact Person (if different from above):	
J. Dam Owner's or Contact Person's Phone Numbers:	Home (803_) 5817643
	Office ()
K. Dam Owner's or Contact Person's mailing address:	Other ()
Address 1 PO BOX 1008	
\(\text{\tint{\text{\tint{\text{\tin}\text{\text{\text{\text{\text{\text{\text{\text{\text{\ti}\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\tin}\text{\tin}\tint{\text{\text{\text{\text{\text{\texi}\text{\text{\text{\text{\texi}\tint{\text{\texi}\tint{\text{\texi}\text{\texi}\tin}\tint{\text{\texi}\text{\texit{\texi}\tint{\texi}\text{\texi}\ti	
Address 2 (optional)	2 200
City, State \(\)	Zip Code Z9 XII
te.	
Section II (Dam Condition)	
General Condition Assessment (Select one of the following	ing):
a) Satisfactory b) Fair c) Poor	d) Unsatisfactory e) Not Rated
Section III (Dam Inspection Checklist)	
A. Dam Crest	
i. Vegetation (grass, trees weeds)?	**************************************
ii. Animal activity observed?	
iii. Any obvious alteration or repairs made?	
iv. Erosion noticed on crest?	e 8
v. Any visible settlement, misalignment or cracks? DICH MALL SUVE does not get worse.	urc 8, should be monitored
DHEC 2604 (Rev 11/2011)	

12.	Upstream Slope
i.	Vegetation (grass, trees weeds)? Wevall Fine large Stump located
<i>∐</i> X ii.	Vegetation (grass, trees weeds)? Overall Fine large stump located her supershall be carefully removed a restribute Animal activity observed? June
iii.	Any obvious alterations or repairs made? YES Stump from the cut
iv.	Erosion observed on upstream slope?
٧.	Settlement or cracks visible in slope?
	Down Stream Slope Vegetation (grass, trees weeds)? Small trees Should be removed
ii.	Animal activity observed?
iii.	Any obvious alterations or repairs made?
iv.	Erosion observed on down stream slope?
V. 3	Settlement or cracks visible in slope? Sloughing in several areas
vi.	Toe drains flowing?
D. Pı	rimary Spillway ny visible deterioration of structure?
ii. Is	s there an obvious need to repair or replace trash rack?
iii. <i>F</i>	Any noticeable problems with debris? ρ
iv. I	s valve or gate present?
	utlet Pipe ny water visibly flowing or leaking outside of the discharge pipe?
ii. D	escribe any deflection or damage observed to the pipe:
iii. V	isible condition of outlet channel:
	xiliary (Emergency) Spillway ticeable obstructions to flow?
. Not	ficeable obstructions to flow?
. No	ticeable obstructions to flow?
An An	imal activity observed?


F. Auxiliary (Emergency) Spillway continued v. If applicable, any observed exposure of rebar reinforcement?
vi. If applicable, any visible leakage below concrete spillway?
H. Downstream/Hazard Class Issues i. Any noticeable changes immediately downstream of the dam that affects the hazard classification?
i. Emergency Action Plan (EAP) i. Emergency Action Plan provided by owner? Provided, department needs
ii. Does EAP contains emergency alert notification plan? If so, when was it last updated?
iii. Does EAP contain specific actions to take if the dam has failed or is near failure?
Section IV (Conclusions)
General comments and recommendations:
and well maintained.
* The strings on the upstream should be removed and
A Change in twenther form is included if adjustment
have been made.
A Dease update the Emurgency Action Plan Included
as well and send back to my office
as were one some race to my once.
3

Preliminary Dam Inspection Disclaimer:

The information contained in the preliminary inspection report is intended as an aid to identify those dams that require maintenance and/or repair actions to reduce their danger to human life or property only. It is not intended as professional engineering or consulting advice for conditions or situations present at individual dams. It is not a substitute for a detailed inspection, nor does it replace the need for services provided by registered professional engineers. If your dam is experiencing an unusual situation consult with engineering professionals to find an appropriate remedy. Preliminary inspections conducted by South Carolina Department of Health and Environmental Control (the Department) are provided "AS IS" and "as available", without warranties of any kind, either express or implied. Preliminary inspections consist only of a visual but technical examination of the dam and its appurtenant works. All findings are based solely on visual observations of the inspector at the time of the inspection. Common law holds that the storage of water is a hazardous activity and the Department does not assume any responsibility or risk for your actions or inactions. Dam owners are responsible for the safe operations and maintenance of their impoundment structures.

DHEC 2604 (Rev 11/2011)

D-0224 Pineview Lakes Dam 1





W. Marshall Taylor Jr., Acting Director

Promoting and protecting the health of the public and the environment

February 23, 2014

To:

Pineview Lakes HOA

PO Box 608

Chester, SC 29706

FROM:

Kristen Jones

2475 DHEC RD.

LANCASTER, SC 29720

RE: Re-inspection of Dam D-0225, Pineview Lakes Dam 2, Chester County

To Whom It May Concern:

On December 16, 2014, I conducted a re-inspection of the above referenced dam. I have enclosed a copy of my inspection report with correlating pictures taken from this dam.

Overall, the dam appears to be in POOR condition. Poor conditions are used when uncertainties exist as to critical analysis parameters, which identify a potential dam safety deficiency. Further investigations and studies are necessary. Please, review the contents of my inspection closely and make necessary adjustments listed in Section IV (Conclusions), for general comments and recommendations.

During my inspection, I found the downstream slope to have many issues. I feel that if not properly addressed these problems outlined below, will hinder the stability of the Dam. <u>Please address these concerns</u> with corrective measures, in writing by Friday March 20, 2015.

Concerns:

- the massive amount of erosion on the downstream slope
- debris on the downstream slope
- size of trees located on the downstream slope

If the above items are not sufficiently addressed by the time allowed this matter may be turned over to enforcement for additional actions.

A copy of the Emergency Notification Plan is enclosed, please update and send back to our office. Should the dam experience difficulty, the agencies listed on the Plan should be contacted and may be able to provide assistance.

Provisions in the S.C. Dams and Reservoirs Safety Act require the owner to notify us within 30 days after transferring title or control of his dam to someone else. The notification must include the name and address of the new owner. I am enclosing a blank form for your use in notifying us should control of your dam be transferred.

You will be notified when the next re-inspection of this dam is scheduled, by the Department. Items listed on inspection report should be addressed before the next inspection. If you have any questions or comments, please call me at (803) 285-7461 or email me at <u>joneskl@dhec.sc.gov</u>.

Sincerely,

Kristen Jones

Regional Engineer

Enclosures:

Inspection Report, Site Pictures, Surveillance, Emergency Notification and Action Plan, Notification Form for

Ownership Change

Cc:

File Room



Preliminary Inspection Report for South Carolina Regulated Dams and Impoundment Structures Regulations

R.72-1 through R.72-9

D
2 B. Name of Dam: PINEURUS Lake Dam 2
D. Date of Last Inspection: (//)
F. EQC Regional Office: Lancaste
Regional Engineer
HOA
pers: Home (<u>8)3</u>) <u>581</u> - <u>766</u> <u>3</u>
Office ()
Other ()
ess.
State SC Zip Code 2970e
2.p 0000
the following):
? hone
the following): or

١.	Upstream Slope Vegetation (grass, trees weeds)? Well maintained
ii.	Animal activity observed? MONC
iii	Any obvious alterations or repairs made? MC
iv	Erosion observed on upstream slope?
٧.	Settlement or cracks visible in slope? NOVE
i. _V:	Down Stream Slope Vegetation (grass, trees weeds)? Cut timber located on clownstrements of the street and counstrements of the street and counstrements of the street and t
iii.	Any obvious alterations or repairs made?
iv.	Erosion observed on down stream slope? YES MUSSIVE PROSION
V.	Settlement or cracks visible in slope?
vi.	Toe drains flowing?
	rimary Spillway ny visible deterioration of structure?
i. A	s there an obvious need to repair or replace trash rack? Any noticeable problems with debris?
i. A	s there an obvious need to repair or replace trash rack? Any noticeable problems with debris?
i. A	s there an obvious need to repair or replace trash rack? Any noticeable problems with debris?
i. A ii. I iii	s there an obvious need to repair or replace trash rack? Any noticeable problems with debris?
i. A	s there an obvious need to repair or replace trash rack? Any noticeable problems with debris? Is valve or gate present?
i. A ii. I iii iv. i. A iii. E	Any noticeable problems with debris? Is valve or gate present? In the problem of structure? I
i. A ii. I ii. I iv. i. A ii. L	Any noticeable problems with debris? Surface an obvious need to repair or replace trash rack? Any noticeable problems with debris? Surface an obvious need to repair or replace trash rack? Surface any noticeable problems with debris? Surface any deflection or leaking outside of the discharge pipe? Surface any deflection or damage observed to the pipe: Surface any deflection or damage observed to the pipe: Surface any deflection or outlet channel: Surface any deflection or outlet channel: Surface any deflection or outlet channel: Surface any deflection of outlet channel: Surface any deflection or outlet channe
i. A ii. I iii. \ iv. i. A iii. C	Is valve or gate present? Sutlet Pipe In water visibly flowing or leaking outside of the discharge pipe? Describe any deflection or damage observed to the pipe: Visible condition of outlet channel: Survey of the discharge pipe? Visible condition of outlet channel: Survey of the discharge pipe? Visible condition of outlet channel: Survey of the discharge pipe? Visible condition of outlet channel: Survey of the discharge pipe? Visible condition of outlet channel: Survey of the discharge pipe? Visible condition of outlet channel: Survey of the discharge pipe? Visible condition of outlet channel: Survey of the discharge pipe? Visible condition of outlet channel: Survey of the discharge pipe? Visible condition of outlet channel: Survey of the discharge pipe? Visible condition of outlet channel: Survey of the discharge pipe? Visible condition of outlet channel: Survey of the discharge pipe? Visible condition of outlet channel: Survey of the discharge pipe? Visible condition of outlet channel: Survey of the discharge pipe? Visible condition of outlet channel: Survey of the discharge pipe? Visible condition of outlet channel: Survey of the discharge pipe? Visible condition of outlet channel: Survey of the discharge pipe? Visible condition of outlet channel: Survey of the discharge pipe? Visible condition of outlet channel: Survey of the discharge pipe? Visible condition of outlet channel: Survey of the discharge pipe?


v. II applicabl	e, any observed exposure of rebar reinforcement?
vi. If applicab	le, any visible leakage below concrete spillway?
	m/Hazard Class Issues ible changes immediately downstream of the dam that affects the hazard classification? മാധ
	whe changes infinediately downstream of the dam that affects the flazard classification?
. Emergency	Action Plan (EAP)
i. Emergency	Action Plan provided by owner? Phyladed, department needs
ii. Does EAP	contains emergency alert notification plan? If so, when was it last updated?
iii. Does EAP	contain specific actions to take if the dam has failed or is near failure?
Camaral a a	Conclusions)
General com	ments and recommendations: a rating of poor due to the downstream slape.
* Awen	ments and recommendations:
→ Gwen -evc	ments and recommendations: a vating of poor due to the downstream slope. such should be addressed ussive trees should be removed thire slope should be extrevaluated for Stublity
A Awen -eva - m - ev	ments and recommendations: a vating of pool due to the downstream slope. such should be addressed ussive trees should be removed thire slope should be extrevaluated for Stublity of PE (professional engineer)
A Awen -eva - m - ev	ments and recommendations: a vating of pool due to the downstream slope. sion should be addressed ussive trees should be removed thire slope should be extreevaluated for Stublity and PE I professional engineer) nange in ownership Form has been included for
A Awen -eva - m - ev	ments and recommendations: a vating of pour due to the downstream slope. sion should be addressed ussive trees should be removed thire slope should be extrevaluated for Stublity of any PE (professional engineer) nange in ownership form has been included for ahons if needed
A Awen -eva - m - ev	ments and recommendations: a vating of poor due to the downstream slope. sun should be addressed ussive trees should be removed thire slope should be extrevaluated for Stubilty hange in ownership Form has been included for whoms it needed margency Achim Plan has also been included eds to be updated and sent back to the departness.
A Given - eve - ev	ments and recommendations: a vating of pool due to the downstream slope. sion should be addressed ussive trees should be removed thire slope should be extrevaluated for Stublity and PE (professional engineer) nange in ownership form has been included for shows if needed margency Action Plan has also been included

Preliminary Dam Inspection Disclaimer:

The information contained in the preliminary inspection report is intended as an aid to identify those dams that require maintenance and/or repair actions to reduce their danger to human life or property only. It is not intended as professional engineering or consulting advice for conditions or situations present at individual dams. It is not a substitute for a detailed inspection, nor does it replace the need for services provided by registered professional engineers. If your dam is experiencing an unusual situation consult with engineering professionals to find an appropriate remedy. Preliminary inspections conducted by South Carolina Department of Health and Environmental Control (the Department) are provided "AS IS" and "as available", without warranties of any kind, either express or implied. Preliminary inspections consist only of a visual but technical examination of the dam and its appurtenant works. All findings are based solely on visual observations of the inspector at the time of the inspection. Common law holds that the storage of water is a hazardous activity and the Department does not assume any responsibility or risk for your actions or inactions. Dam owners are responsible for the safe operations and maintenance of their impoundment structures.

DHEC 2604 (Rev 11/2011)

D-0225 Pineview Lakes Dam 2



10



South Carolina Department of Health and Environmental Control

CATAWBA DISTRICT ENVIRONMENTAL QUALITY CONTROL

Serving Chester, Lancaster, and York Counties

June 27, 2001

Mr. Isom Westbrook 1375 Crossland Road Clover, S.C. 29710

RE: Reinspection of Adam's Pond Dam, D-1215, York Co.

Dear Mr. Westbrook:

On December 8, 2000, I conducted a reinspection of the above referenced dam. Overall the dam appeared structurally sound, continue control of the growth of trees and shrubs on the slopes of the dam.

A copy of the Emergency Notification Plan is enclosed for your use. Should the dam experience difficulty, the agencies listed on the Plan can provide assistance in possibly closing down stream roads or contacting down stream property owners. These agencies should be contacted in case of an emergency occurs.

Provisions in the S. C. Dams and Reservoirs Safety Act require the owner to notify us within 30 days after transferring title or control of his dam to someone else. The notification must include the name and address of the new owner. I am enclosing a blank form for your use in notifying us should control of your dams be transferred.

You will be notified when the next reinspection of this dam is scheduled.

District E

E Vielie Blanton

1347 Crossland Rd

Clover SC 29710

222 4602 H

222 4602 H

627 2334 all

of Water Fac. Compli

P.O. Box 100 Fort Lawn, SC 29714



C. Earl Hunter, Commissioner

Promoting and protecting the health of the public and the environment.

November 25, 2008

Leroy Springs & Co Inc Mr. Bill Steele 2201 OLD NATION RD Fort Mill, SC 29716

RE: Re-inspection of LAKE HAIGLER DAM, D-1238, York County

Dear Mr. Bill Steele:

Thank you for taking the time to show me the Greenway and the Lake Haigler Dam. The area was impressive.

On November 9, 2008, I conducted a re-inspection of the above referenced dam with Mr. Bill Steele. Overall, the dam appears structurally sound Shrubs should be removed from downstream slope of the dam. Trees with 6" diameter or more should not be removed.

An inspection report is enclosed.

A copy of the Emergency Notification Plan is enclosed for your use. Should the dam experience difficulty, the agencies listed on the Plan can provide assistance in possibly closing down stream roads or contacting down stream property owners. These agencies should be contacted in case if an emergency occurs.

Provisions in the S.C. Dams and Reservoirs Safety Act require the owner to notify us within 30 days after transferring title or control of his dam to someone else. The notification must include the name and address of the new owner. I am enclosing a blank form for your use in notifying us should control of your dams be transferred.

You will be notified when the next re-inspection of this dam is scheduled.

Sincerely,

Greg Harrington

District Engineer

Cc: Susan Scott - File Room

NOTIFICATION OF OWNERSHIP CHANGE S.C. REGULATED DAM

The ownership of Dam LAKE HAIGLER DAM, D-1238 in (Name of Dam) York County has changed. The new owner(s) are:

Owner 1 *:	
Address:	
City, State, Zip:	
Telephone Number:	
Owner 2: (If applicable)	
Address:	
City, State, Zip	
Telephone Number:	
•	
Additional Owner (If applicable)	
Address:	
City, State, Zip:	
Telephone Number:	
* If owner is a corporation, give name	of principal contact person:
1 (100) (100) (100) (100) (100)	
(Previous Owner's Signature)	
(Previous Owner's Name)	
,	
Previous Owner's Address	
Mail Above Notification To:	S. C. Department of Health and Environmental Control
	Dams and Reservoirs Safety
	2600 Bull St.
	Columbia, SC 29201
NOTE: Failure to notify the S.C. Departr	nent of Health and Environmental Control within 30 days of ownership transfer can result in
a fine of \$ 100 - \$1000.	•
+ +	
DHEC 2605 (10/08)	
DIIFO TODO (101 00)	la contraction de la contracti



W. Marshall Taylor Jr., Acting Director Promoting and protecting the health of the public and the environment February 19, 2014

To:

Mr. R.T. Dooley

P.O. Box 11372

Charlotte, NC 28220

FROM:

Kristen Jones

2475 DHEC Rd.

Lancaster, SC 29720

RE: Reinspection of Dam D-1778, Sherrill Pond Dam, Lancaster Co.

Dear Mr. Dooley:

On September 19, 2014, I conducted a reinspection of the above referenced dam. I have enclosed a copy of my inspection report with correlating pictures taken from this dam.

Overall, the dam appears to be in FAIR condition. This rating is assigned to dams where there is no existing safety deficiencies recognized for normal loading conditions. Please, review the contents of my inspection closely and make necessary adjustments listed in Section IV (Conclusions), for general comments and recommendations.

A copy of the Emergency Notification Plan is enclosed, please update and send back to our office. Should the dam experience difficulty, the agencies listed on the Plan should be contacted and may be able to provide assistance.

Provisions in the S.C. Dams and Reservoirs Safety Act require the owner to notify us within 30 days after transferring title or control of his dam to someone else. The notification must include the name and address of the new owner. I am enclosing a blank form for your use in notifying us should control of your dam be transferred.

You will be notified when the next reinspection of this dam is scheduled, by the Department. Items listed on inspection report should be addressed before the next inspection. If you have any questions or comments, please call me at (803) 285-7461 or email me at joneskl@dhec.sc.gov.

Sincerely.

Kristen Jones

Regional Engineer

Enclosures:

Inspection Report, Site Pictures, Surveillance, Emergency Notification and Action Plan, Notification Form for

Ownership Change

Cc:

John Poole, P.E. SCDHEC Dam Safety



Preliminary Inspection Report for South Carolina Regulated Dams and Impoundment Structures Regulations

R.72-1 through R.72-9

Section I (Owner's Information)
A. Dam Number: D 1778 & Hazard Class CP B. Name of Dam: Sherrill Pond
C. Inspection Date (//20 & Time: D. Date of Last Inspection: (//20)
E. Location-County/City: Lancaster Lancaster F. EQC Regional Office: Lancaster
G. Inspector's Name: Kristen Janes - Regional Engineer
H. Owner's Name: RT Danley
I. Contact Person (if different from above):
J. Dam Owner's or Contact Person's Phone Numbers: Home (803) 329 - 4522
Office ()
Other ()
K. Dam Owner's or Contact Person's mailing address: Address 1 P.O. Box 1372
Address 2 (optional)
City Charlotte, State NC zip Code 28 700
Section II (Dam Condition)
General Condition Assessment (Select one of the following):
a) Satisfactory b) Fair 💢 c) Poor d) Unsatisfactory e) Not Rated
Section III (Dam Inspection Checklist)
A. Dam Crest i. Vegetation (grass, trees weeds)? _Υυαλ
ii. Animal activity observed?
iii. Any obvious alteration or repairs made?
iv. Erosion noticed on crest? Tye hacks
v. Any visible settlement, misalignment or cracks? NOVA
DHEC 2604 (Rev 11/2011)

h	Upstream Slope Vegetation (grass, trees weeds)? Lits of Vegetation, (and be cut to
11	Animal activity observed? Les, Twy ties, Trugs
ii	. Any obvious alterations or repairs made? YUV
iv	Erosion observed on upstream slope? NUM I high grass
V.	Settlement or cracks visible in slope? Steep not much of a slope
L	Down Stream Slope Vegetation (grass, trees weeds)? Nigh Vegetation, Should be cut lowed to upstream Tlope Animal activity observed? hono
iii.	Any obvious alterations or repairs made?
iv.	Erosion observed on down stream slope?
٧.	Settlement or cracks visible in slope?
vi.	Toe drains flowing? (Mid hot year)
). P	rimary Spillway Any visible deterioration of structure?
ii. I	
	s there an obvious need to repair or replace trash rack?
	Any noticeable problems with debris?
iii.	18/7
iii. iv.	Any noticeable problems with debris?
iii. iv. E. C i. A	Any noticeable problems with debris? Solve or gate present? What Solve the discharge pipe?
iii. iv. E. C i. A	Any noticeable problems with debris? Solve or gate present? Solvettet Pipe In water visibly flowing or leaking outside of the discharge pipe?
iii. iv. ii. C iii. C	Any noticeable problems with debris? Is valve or gate present? In the problems with debris? I
iii. E iii. E iii. L iii. No	Any noticeable problems with debris? Is valve or gate present? In the problems with debris? In the problems with debris. I
iii. E. C. ii. A. iii. V.	Any noticeable problems with debris? Is valve or gate present? In the Pipe I


v. If applic	-10//
vi. If appli	cable, any visible leakage below concrete spillway?
	ream/Hazard Class Issues ceable changes immediately downstream of the dam that affects the hazard classification?
	ncy Action Plan (EAP) ncy Action Plan provided by owner?
ii. Does E	AP contains emergency alert notification plan? If so, when was it last updated?
iii. Does E	AP contain specific actions to take if the dam has failed or is near failure?
MANA	I do to car liceto
Spare	I dam well maintuined would like to see vigeto shorter on both supes at the dam. with landscaping team advised me that is cut t every two weeks
Cut Spoke alaw Emer Send	shorter on both slupes of the dam.
Spore about Emer Send Chan	shorter on both slupes of the dam. with landscaping team advised me that is cut tevery two weeks
Spore about Emer Send Chan	shorter on both supes at the dam. with landscaping team advised me that is cut tevery two weeks igency Action Plan is included; pleasu update and back ge of ownership also included if there has been

Preliminary Dam Inspection Disclaimer:

The information contained in the preliminary inspection report is intended as an aid to identify those dams that require maintenance and/or repair actions to reduce their danger to human life or property only. It is not intended as professional engineering or consulting advice for conditions or situations present at individual dams. It is not a substitute for a detailed inspection, nor does it replace the need for services provided by registered professional engineers. If your dam is experiencing an unusual situation consult with engineering professionals to find an appropriate remedy. Preliminary inspections conducted by South Carolina Department of Health and Environmental Control (the Department) are provided "AS IS" and "as available", without warranties of any kind, either express or implied. Preliminary inspections consist only of a visual but technical examination of the dam and its appurtenant works. All findings are based solely on visual observations of the inspector at the time of the inspection. Common law holds that the storage of water is a hazardous activity and the Department does not assume any responsibility or risk for your actions or inactions. Dam owners are responsible for the safe operations and maintenance of their impoundment structures.

DHEC 2604 (Rev 11/2011)

D-1778 Sherrill Pond Dam





C. Earl Hunter, Commissioner
Promotiog and protecting the health of the public and the environment.

January 2, 2009

Close Family Real Estate Partnership #1 Mr. Close P.O. Box 460 Lancaster, SC 29720

RE: Re-inspection of LAKE PATRICIA DAM, D 3480, York County

Dear Mr. Close:

On December 17, 2008, I conducted a re-inspection of the above referenced dam. Overall, the dam appears structurally sound Shrubs and trees should be removed from downstream slope of the dam. Trees with 6" diameter or more should not be removed.

An inspection report is enclosed.

A copy of the Emergency Notification Plan is enclosed for your use. Should the dam experience difficulty, the agencies listed on the Plan can provide assistance in possibly closing down stream roads or contacting down stream property owners. These agencies should be contacted in case if an emergency occurs.

Provisions in the S.C. Dams and Reservoirs Safety Act require the owner to notify us within 30 days after transferring title or control of his dam to someone else. The notification must include the name and address of the new owner. I am enclosing a blank form for your use in notifying us should control of your dams be transferred.

You will be notified when the next re-inspection of this dam is scheduled.

Sincerely,

Greg Harrington District Engineer

Cc: Susan Scott - File Room

Date: 1/2/08	
Dam: D 3480	
Lappura S	
Representatives of SCOHEC Present: Greg Harrington	
	91
Others Present:	-
Listed of noted deficiencies or items requiring correction/checking:	
On December 17, 2008, I conducted a re-inspection of the	
above referenced dam. Overall, the dam appears structurally sound Shrubs and trees should be removed from downstream	
slope of the dam. Trees with 6" diameter or more should not	
be removed.	
List of previously noted items still uncorrected and dates previously noted:	
9	
Emergency Action Plan Updated: X -Yes No	
	Greg Harrington
	DHEC Person Completing Form
DICC 2007 (ID /DB)	
DHEC 2604 (10/08)	

NOTIFICATION OF OWNERSHIP CHANGE S.C. REGULATED DAM

The ownership of Dam LAKE PATRICIA DAM, D 3480in (Name of Dam) York County has changed. The new owner(s) are:

Owner 1 *:	
Address:	
City, State, Zip:	
Telephone Number:	
Owner 2: (If applicable)	
Address:	
City, State, Zip	
Telephone Number:	
Additional Owner (If applicable)	
Address:	
City, State, Zip:	
Telephone Number:	
* If owner is a corporation, give name	of principal contact person:
(Previous Owner's Signature)	
(Previous Owner's Name)	
Previous Owner's Address	÷
Mail Above Notification To:	S. C. Department of Health and Environmental Control
	Dams and Reservoirs Safety
	2600 Bull St.
	Columbia, SC 29201
NOTE, Calling to matter the C.C. Danner	
	nent of Health and Environmental Control within 30 days of ownership transfer can result in
a fine of \$ 100 - \$1000.	
DHEC 2605 (10/08)	



Proporting and protecting the health of the public and the environment,

February 4, 2009

SPRINGLAND ASSOCIATES LLC ATTENTION: MR. Will Close 1 PEACH LANE FORT MILL, SC 29715

RE: Re-inspection of SPRINGLAND - GIBSON POND DAM, D-3644, York County

Dear Mr. Will Close:

On December 30, 2008, I conducted a re-inspection of the above referenced dam. Overall the dam appears structurally sound, shrubs and small trees should be removed from the downstream slope of the dam. Trees with 6" diameter or more should not be removed.

A copy of the Emergency Notification Plan is enclosed for your use. Should the dam experience difficulty, the agencies listed on the Plan can provide assistance in possibly closing down stream roads or contacting down stream property owners. These agencies should be contacted in case if an emergency occurs.

Provisions in the S.C. Dams and Reservoirs Safety Act require the owner to notify us within 30 days after transferring title or control of his dam to someone else. The notification must include the name and address of the new owner. I am enclosing a blank form for your use in notifying us should control of your dams be transferred.

You will be notified when the next re-inspection of this dam is scheduled.

Sincerely,

Greg Harrington District Engineer

Cc: Susan Scott – File Room

D. 10 Man 4011 10121	
Date: 12/30/2008 MULT 12/30/2008	
Dam: D-3644	
Representatives of SCOHEC Present: Greg Harrington	
Others Present:	
Listed of noted deficiencies or items requiring correction/checking:	
On December 30, 2008, I conducted a re-inspection of the	
above referenced dam. Overall the dam appears structurally	
sound, shrubs and small trees should be removed from the	
downstream slope of the dam. Trees with 6" diameter or more	
should not be removed.	
	4-2
List of previously noted items still uncorrected and dates previously noted:	
Same	
dallic	
Emergency Action Plan Updated: X -Yes No	
	N. C.
	Greg Harrington
	OHEC Person Completing Form
DHEC 2604 (10/08)	

NOTIFICATION OF OWNERSHIP CHANGE S.C. REGULATED DAM

The ownership of SPRINGLAND - GIBSON POND DAM, D-3644, York County has changed. The new owner(s) are:

	The state of the s
Owner 1 *:	
ALL	
Address:	
City, State, Zip:	
uity, state, zip.	
Telephone Number:	
,	
Owner 2: (If applicable)	
Address:	
Cia., Ca.a., 7i	
City, State, Zip	
Telephone Number:	
Additional Owner (If applicable)	
Address:	
City, State, Zip:	
Telephone Number:	
* If owner is a corporation, give name	of principal contact person:
(B	
(Previous Owner's Signature)	
(Previous Owner's Name)	
(Li.sainna nailsi. 2 idailis)	
Previous Owner's Address	
Mail Above Notification To:	S. C. Department of Health and Environmental Control
	Dams and Reservoirs Safety
	2600 Bull St.
	Columbia, SC 29201
	nent of Health and Environmental Control within 30 days of ownership transfer can result in
a fine of \$ 100 - \$1000.	
DHEC 2605 (10/08)	
DIILU LUUU (IU/ UU/	



Promoting and protecting the health of the public and the environment.

February 24, 2011

Mr. Fred Chuck PE Forest Lake Comm Club 401 Lake View Drive Fort Mill, SC 29715

RE: Re-inspection of FOREST LAKE DAM, D 3645, York County

Dear Mr. Fred Chuck PE:

On 12/29/10, I conducted a re-inspection of the above referenced dam. Overall, the dam appears to be maintained except for the outlet structure. Part of the outlet structure has broken off, and the remainder of the structure is being compromised by erosion. Please repair this structure by May 30, 2011. If you would like to meet me at the dam, please call me at 803-385-7461.

An inspection report is enclosed.

A copy of the Emergency Notification Plan is enclosed for your use. Should the dam experience difficulty, the agencies listed on the Plan can provide assistance in possibly closing down stream roads or contacting down stream property owners. These agencies should be contacted in case if an emergency occurs.

Provisions in the S.C. Dams and Reservoirs Safety Act require the owner to notify us within 30 days after transferring title or control of his dam to someone else. The notification must include the name and address of the new owner. I am enclosing a blank form for your use in notifying us should control of your dams be transferred.

You will be notified when the next re-inspection of this dam is scheduled.

Sincepely

District Engineer

Divider Eligible.

Cc: Susan Scott – File Room

Date: 12/29/10	
Dam: D 3645	
ини. D 3043	
Representatives of SCDHEC Present: Greg Harrington	
Others Present:	
Listed of noted deficiencies or items requiring correction/checking:	
On 12/29/10, Greg Harrington conducted a re-inspection of the above referenced dam. Overall, the dam appears to be	
maintained except for the outlet structure. Part of the outlet	
structure has broken off, and the remainder of the structure is	
being compromised by erosion	
List of previously noted items still uncorrected and dates previously noted:	
Proposition Analysis Plant Land Land Land Land Land Land Land Land	
mergency Action Plan Updated: X -Yes No	
	Greg Harrington
	DHEC Person Completing Form
IEC 2604 (10/08)	



Catherine B. Templeton, Director Promoting and protecting the health of the public and the environment Certified Delivery

May 30, 2014

Kevin Hart Rock Hill Country Club 600 Country Club Drive Rock Hill, SC 29730

RE:

Rock Hill Country Club- SC Noname 4614 (D-3671) Preliminary Inspection Results Significant Hazard, York County

Dear Mr. Hart:

The Department has the responsibility and authority to routinely inspect regulated dams. During our site visit on May 2, 2014, Matthew Hauser a staff member from the Bureau of Water and I met to perform a preliminary inspection of the above referenced dam. Inspection reports and photographs from this inspection are enclosed. The following issues were discovered during the inspection:

The overall condition for this dam was not rated. This rating is assigned to dams where it is not possible to assess the dam's condition due to site constraints on visibility the day of inspection. Remedial action is necessary and further analysis is required to determine the appropriate response measures. Please address the comments below in writing by Monday, June 30,2014.

Comments:

- 1. Massive vegetation throughout the entire dam. Obtain permits to safely clear vegetation, properly cut and re-stabilize the dam. (See Included Dams and Reservoirs Safety Act Regulations)
- 2. Deleterious vegetation, such as dead stumps upstream/downstream, need to be properly removed from the dam and then re-graded.
- 3. Trees located in the spillway, should be removed as they may cause turbulent flow, causing erosion of the channel.

Additionally, I have included the DHEC Form 2606 – The Surveillance, Emergency Notification and Action Plan for South Carolina Regulated Dams this needs to be filled out and submitted along with the Notification Form for Ownership Change, if needed.

If the above items are not sufficiently addressed by the time allowed, this matter will be turned over to enforcement for additional actions and possible fines.

If you have any questions or comments regarding these requirements, please call me at (803) 285-7461 or email me at joneskl@dhec.sc.gov.

Sincerely,

Kristen Jones Regional Engineer Red FoxTrail (34.886473, -81.036237)



Preliminary Inspection Report for South Carolina Regulated Dams and Impoundment Structures Regulations R.72-1 through R.72-9

Section I (Owner's Information)	(ROCK Hill Country Club
A. Dam Number: D 3671 & Hazard Class C2	B. Name of Dam: SC Nonama 4614
C. Inspection Date (5/2/20) & Time: 100 pm	D. Date of Last Inspection: $(12/3/08)$
E. Location-County/City: YWK / PULLTIL	F. EQC Regional Office: Lan LastCV
G. Inspector's Name: Khaleh Jules / 110	ithew thruser
H. Owner's Name: ROCK HILL (MINTY	(lub
I. Contact Person (if different from above):	Hav +
J. Dam Owner's or Contact Person's Phone Numbers:	Home (\$13) 328 -1894
Khart @ rockhill countryclub.net	Office ()
K. Dam Owner's or Contact Person's mailing address:	Other ()
Address 1 (00) (OUNTY Club D	in VP
U	
Address 2 (optional)	C Zip Code 79730
City KOCK TILL , State S	Zip Code 29773C
Section II (Dam Condition)	
General Condition Assessment (Select one of the follow	ing):
a) Satisfactory b) Fair c) Poor	d) Unsatisfactory e) Not Rated
Section III (Dam Inspection Checklist)	d not inspect see
A. Dam Crest i. Vegetation (grass, trees weeds)?	at lacked"
ii. Animal activity observed?	
iii. Any obvious alteration or repairs made?	
iv Freeign noticed on crest?	
v. Any visible settlement, misalignment or cracks?	
DHEC 2604 (Rev 11/2011)	

	pstream Slope /egetation (grass, trees weeds)?
	Animal activity observed?
iii.	Any obvious alterations or repairs made?
iv.	Erosion observed on upstream slope?
v. 5	Settlement or cracks visible in slope?
i. \	bwn Stream Slope /egetation (grass, trees weeds)?
ii. /	Animal activity observed?
iii.	Any obvious alterations or repairs made?
iv. I	Erosion observed on down stream slope?
v. S	ettlement or cracks visible in slope?
vi.	oe drains flowing?
	rate, and any turbidity or color within the flow:
	imary Spillway ny visible deterioration of structure?
i. Aı	dille i det alienetien et et met anno
i. Aı	there an obvious need to repair or replace trash rack?
i. Aı ii. Is	there an obvious need to repair or replace trash rack?
ii. Is iii. A iii. A	there an obvious need to repair or replace trash rack? In noticeable problems with debris?
i. A	there an obvious need to repair or replace trash rack? In noticeable problems with debris? In valve or gate present? In the problems with debris?
ii. Is iii. A iii. A iv. I: i. Ar ii. D	there an obvious need to repair or replace trash rack? In noticeable problems with debris? In valve or gate present? In the problems with debris? In the problems with debris?
ii. Is iii. Is iii. A iii. A iii. A iv. I: ii. Ar iii. D	there an obvious need to repair or replace trash rack? In noticeable problems with debris? In valve or gate present? Itlet Pipe In water visibly flowing or leaking outside of the discharge pipe? Describe any deflection or damage observed to the pipe:
ii. As iii. Is iii. A iii. Ar iii. D iiii. V	there an obvious need to repair or replace trash rack? In noticeable problems with debris? In valve or gate present? Itlet Pipe In y water visibly flowing or leaking outside of the discharge pipe? Describe any deflection or damage observed to the pipe: Disible condition of outlet channel: Exiliary (Emergency) Spillway
ii. As iii. Is iii. A iv. Is ii. Ar iii. D	there an obvious need to repair or replace trash rack? In noticeable problems with debris? Itlet Pipe In water visibly flowing or leaking outside of the discharge pipe? Describe any deflection or damage observed to the pipe: Disible condition of outlet channel: Exiliary (Emergency) Spillway ticeable obstructions to flow?


v. If applicable, any observed exposure of rebar reinforcement?	
vi. If applicable, any visible leakage below concrete spillway? H. Downstream/Hazard Class Issues i. Any noticeable changes immediately downstream of the dam that affects the hazard classification?	
ii. Does EAP contains	emergency alert notification plan? If so, when was it last updated?
iii. Does EAP contain	specific actions to take if the dam has failed or is near failure?
	nd recommendations:
	
	
	
	
Section IV (Conclu	
	
	

Preliminary Dam Inspection Disclaimer:

The information contained in the preliminary inspection report is intended as an aid to identify those dams that require maintenance and/or repair actions to reduce their danger to human life or property only. It is not intended as professional engineering or consulting advice for conditions or situations present at individual dams. It is not a substitute for a detailed inspection, nor does it replace the need for services provided by registered professional engineers. If your dam is experiencing an unusual situation consult with engineering professionals to find an appropriate remedy. Preliminary inspections conducted by South Carolina Department of Health and Environmental Control (the Department) are provided "AS IS" and "as available", without warranties of any kind, either express or implied. Preliminary inspections consist only of a visual but technical examination of the dam and its appurtenant works. All findings are based solely on visual observations of the inspector at the time of the inspection. Common law holds that the storage of water is a hazardous activity and the Department does not assume any responsibility or risk for your actions or inactions. Dam owners are responsible for the safe operations and maintenance of their impoundment structures.

DHEC 2604 (Rev 11/2011)

Pictures Taken of Rock Hill Country Club D-3671 May 2, 2014



Date: 12/17/08	
Dam: D 3645	
Dam: D 3643	
Representatives of SCDHEC Present: Joe Faris	
Dalance Discount	
Others Present:	
	•
Listed of noted deficiencies or items requiring correction/checking:	
Joe Faris conducted a re-inspection of the above referenced dam. Overall, the dam appears structurally sound and well	4
maintained.	
*	
List of previously noted items still uncorrected and dates previously noted:	
Same	
*	
Emergency Action Plan Updated: X -Yes No	
Cine gency Action Figure Opunica. A -165 No	
	Joe Faris
	DHEC Person Completing Form
DHEC 2604 (ID/08)	

NOTIFICATION OF OWNERSHIP CHANGE S.C. REGULATED DAM

The ownership of FOREST LAKE DAM, D 3645, York County has changed. The new owner(s) are:

r	
Owner 1 *:	
Address:	
Λ	
City, State, Zip:	
Telephone Number:	
Owner 2: (If applicable)	
W	
Address:	
City, State, Zip	
Telephone Number:	
Additional Owner (If applicable)	^
Address:	
City, State, Zip:	
Telephone Number:	
* If owner is a corporation, give name	of principal contact person:
(Previous Owner's Signature)	
(Previous Owner's Name)	
Previous Owner's Address	
Mail Above Notification To:	S. C. Department of Health and Environmental Control
	Dams and Reservoirs Safety
	2600 Bull St.
	Columbia, SC 29201
NULL: Failure to notify the C.C. Deserte	nent of Health and Environmental Control within 30 days of ownership transfer can result in
a fine of \$ 100 - \$1000.	neur or region and ellan millielled anim of within an gold of amile suit it guister. Call Lezalt III
a line of Q loo - Qlobb.	
NUCC 2006 (IO (OO)	
DHEC 2605 (10/08)	



W. Marshall Taylor Jr., Acting Director

Promoting and protecting the health of the public and the environment

February 19, 2014

To:

Donald Christopher

1831 MT. HOLLY DR. ROCK HILL, SC 29730

FROM:

Kristen Jones

2475 DHEC RD.

LANCASTER, SC 29720

RE: Re-inspection of Dam D-3672, Marshall Dam, York County

Dear Mr. Christopher:

On September 19, 2014, I conducted a re-inspection of the above referenced dam. I have enclosed a copy of my inspection report with correlating pictures taken from this dam.

Overall, the dam appears to be in FAIR condition. This rating is assigned to dams where there is no existing safety deficiencies recognized for normal loading conditions. Please, review the contents of my inspection closely and make necessary adjustments listed in Section IV (Conclusions), for general comments and recommendations.

A copy of the Emergency Notification Plan is enclosed, please update and send back to our office. Should the dam experience difficulty, the agencies listed on the Plan should be contacted and may be able to provide assistance.

Provisions in the S.C. Dams and Reservoirs Safety Act require the owner to notify us within 30 days after transferring title or control of his dam to someone else. The notification must include the name and address of the new owner. I am enclosing a blank form for your use in notifying us should control of your dam be transferred.

You will be notified when the next reinspection of this dam is scheduled, by the Department. Items listed on inspection report should be addressed before the next inspection. If you have any questions or comments, please call me at (803) 285-7461 or email me at joneskl@dhec.sc.gov.

Sincerely,

Kristen Iones

Regional Engineer

Enclosures:

Inspection Report, Site Pictures, Surveillance, Emergency Notification and Action Plan, Notification Form for

Ownership Change

Cc:

File Room



Preliminary Inspection Report for South Carolina Regulated Dams and Impoundment Structures Regulations R.72-1 through R.72-9

Section I (Owner's Information)	
A. Dam Number: D3672 & Hazard Class_C2_	B. Name of Dam:
C. Inspection Date (2/2/2014) & Time:	D. Date of Last Inspection: (/_ /)
E. Location-County/City:/_/_/	F. EQC Regional Office: 1 QINGSTOY
G. Inspector's Name: Kysich Ches - Pagior	val Engineer
H. Owner's Name: Danald Christopher	<u> </u>
I. Contact Person (if different from above):	
J. Dam Owner's or Contact Person's Phone Numbers:	Home (808) 3 29 2534
	Office ()
K. Dam Owner's or Contact Person's mailing address:	Other ()
Address 1 1831 Mt Haly Drive	
Address 2 (optional)	41700
City Rock Hill State S	SC Zip Code 29730_
×	
Section II (Dam Condition)	
General Condition Assessment (Select one of the following	
a) Satisfactory b) Fair c) Poor	d) Unsatisfactory e) Not Rated
Section III (Dam Inspection Checklist)	
i. Animal activity observed?	industs on west may be
iii. Any obvious alteration or repairs made? Von	
iv. Erosion noticed on crest? MOVIL	
v. Any visible settlement, misalignment or cracks? MM	
DHEC 2604 (Rev 11/2011)	


1. \	ostream Slope Vegetation (grass, trees weeds)? <u>VEGETWOOD</u> Should be Cut lower
200	Animal activity observed? NIME
iii.	Any obvious alterations or repairs made? NUML
iv. E	rosion observed on upstream slope?
v. S	ettlement or cracks visible in slope? MON I
C. Do i. Vo	wn Stream Slope egetation (grass, trees weeds)?
ii. A	nimal activity observed? Wille
iii. A	ny obvious alterations or repairs made? 110
iv. E	rosion observed on down stream slope?
v. Se	ttlement or cracks visible in slope?
vi. To	e drains flowing?
i. Any	nary Spillway visible deterioration of structure? PICO mere an obvious need to repair or replace trash rack?
i. Any	visible deterioration of structure? MC
i. Any ii. Is ti iii. Any	visible deterioration of structure? YNO
i. Any ii. Is ti iii. Any iv. Is v	nere an obvious need to repair or replace trash rack? noticeable problems with debris?
i. Any ii. Is ti iii. Any iv. Is v i. Outl	rere an obvious need to repair or replace trash rack? In noticeable problems with debris? In noticeable present? In our gate present?
i. Any ii. Is ti iii. Any iv. Is v iv. Any ii. Any iii. Desc	visible deterioration of structure? Mere an obvious need to repair or replace trash rack? In noticeable problems with debris? Alve or gate present? Policet Pipe Water visibly flowing or leaking outside of the discharge pipe?
i. Any ii. Is ti iii. Any iv. Is v i. Outl i. Any ii. Desc ii. Visil	rere an obvious need to repair or replace trash rack? In noticeable problems with debris? In noticeable problems with de
i. Any ii. Is ti iii. Any iv. Is v i. Outl i. Any ii. Visil Auxili Notice	rere an obvious need to repair or replace trash rack? In noticeable problems with debris? In noticeable problems with de
ii. Is the iii. Any iv. Is with ii. Any ii. Descrit. Visili Notice Anima	rere an obvious need to repair or replace trash rack? In noticeable problems with debris? In noticeable problems with de

vi If applicable any via	ible legicage below congrete collings?	
vi. ii applicable, any vis	ible leakage below concrete spillway? NA	
H. Downstream/Hazard i. Any noticeable chang	Class Issues es immediately downstream of the dam that affects the hazard classification?	
i. Emergency Action Plant i. Emergency Action Plant		
ii. Does EAP contains e	mergency alert notification plan? If so, when was it last updated?	
iii. Does EAP contain sp	pecific actions to take if the dam has failed or is near failure?	
General comments an	d recommendations:	dan ch
General comments an		daunst
General comments an	d recommendations:	daenst
General comments and world little stopes and the bit over all gwal	of sloughing on sloves just monitor	_
sloves sloves valittle bit exercise good provided in	of sloughing on sloves just monitor condition	_
General comments and world little stopes and the bit over all gwal	of sloughing on sloves just monitor condition package is an Energency Notification Plant and Sent back to my office	_
General comments an *** **LYMICH LIVE 510005 PAINTE BIT OVERAL GLOOL PHOVIDED IN	of sloughing on sloves just monitor condition	_
General comments an ***********************************	of sloughing on sloves just monitor condition package is an Energency Notification Plant and Sent back to my office	_
General comments an ***********************************	of sloughing on sloves just monitor condition package is an Energency Notification Plant and Sent back to my office	_

Preliminary Dam Inspection Disclaimer:

The information contained in the preliminary inspection report is intended as an aid to identify those dams that require maintenance and/or repair actions to reduce their danger to human life or property only. It is not intended as professional engineering or consulting advice for conditions or situations present at individual dams. It is not a substitute for a detailed inspection, nor does it replace the need for services provided by registered professional engineers. If your dam is experiencing an unusual situation consult with engineering professionals to find an appropriate remedy. Preliminary inspections conducted by South Carolina Department of Health and Environmental Control (the Department) are provided "AS IS" and "as available", without warranties of any kind, either express or implied. Preliminary inspections consist only of a visual but technical examination of the dam and its appurtenant works. All findings are based solely on visual observations of the inspector at the time of the inspection. Common law holds that the storage of water is a hazardous activity and the Department does not assume any responsibility or risk for your actions or inactions. Dam owners are responsible for the safe operations and maintenance of their impoundment structures.

DHEC 2604 (Rev 11/2011)





Promoting and protecting the health of the public and the environment.

November 24, 2008

York NRCS Mr. John Templeton 13 S CONGRESS ST York, SC 29745

RE: Re-inspection of FISHING CREEK WCD DAM 50, D-3673, York County

Dear Mr. John Templeton:

On October 9, 2008, Joe Faris conducted a re-inspection of the above referenced dam. Vegetation needs to be removed from both slopes. Shrubs should be removed from both the upstream and downstream slopes of the dam. Trees with 6" diameter or more should not be removed. An inspection report is enclosed.

A copy of the Emergency Notification Plan is enclosed for your use. Should the dam experience difficulty, the agencies listed on the Plan can provide assistance in possibly closing down stream roads or contacting down stream property owners. These agencies should be contacted in case if an emergency occurs.

Provisions in the S.C. Dams and Reservoirs Safety Act require the owner to notify us within 30 days after transferring title or control of his dam to someone else. The notification must include the name and address of the new owner. I am enclosing a blank form for your use in notifying us should control of your dams be transferred.

You will be notified when the next re-inspection of this dam is scheduled.

Sincerely,

Greg Harrington

District Engineer

Cc: Susan Scott - File Room

NOTIFICATION OF OWNERSHIP CHANGE S.C. REGULATED DAM

The ownership of Dam D - 3673 FISHING CREEK WCD DAM 50 in (Name of Dam) York County has changed. The new owner(s) are:

Owner 1 *:	
Address:	
City, State, Zip:	
Telephane Number:	
Owner 2: (If applicable)	
Address:	
City, State, Zip	
Telephone Number:	
Additional Owner (If applicable)	
Address:	
City, State, Zip:	
Telephone Number:	
* If owner is a corporation, give name	of principal contact person:
(Previous Owner's Signature)	
(Previous Owner's Name)	
Previous Owner's Address	
Mail Above Notification To:	S. C. Department of Health and Environmental Control
	Dams and Reservoirs Safety
	2600 Bull St.
	Columbia, SC 29201
	nent of Health and Environmental Control within 30 days of ownership transfer can result in
a fine of \$ 100 - \$1000.	
DHEC 2605 (10/08)	

NOTIFICATION OF OWNERSHIP CHANGE S.C. REGULATED DAM

The ownership of Dam D - 3673 FISHING CREEK WCD DAM 50 in (Name of Dam) York County has changed. The new owner(s) are:

Owner 1 *:	
Address:	
City, State, Zip:	
Telephone Number:	
Owner 2: (If applicable)	
Address:	
City, State, Zip	
Telephone Number:	
Additional Owner (If applicable)	
Address:	
City, State, Zip:	
Telephone Number:	
* If owner is a corporation, give name	of principal contact person:
(Previous Owner's Signature)	
(Previous Owner's Name)	
Previous Owner's Address	
Mail Above Notification To:	S. C. Department of Health and Environmental Control
	Dams and Reservoirs Safety
	2600 Bull St.
	Columbia, SC 29201
NOTE: Failure to notify the S.C. Departn	nent of Health and Environmental Control within 30 days of ownership transfer can result in
a fine of \$ 100 - \$1000.	
DHEC 2605 (10/08)	



South Carolina Department of Health and Environmental Control

CATAWBA DISTRICT ENVIRONMENTAL QUALITY CONTROL

Serving Chester, Lancaster, and York Counties

June 21, 1999

Mr. Adron Logan 1464 Darby Road Chester, S.C. 29706

RE: Reinspection of Logan's pond Dam, D-1439; Chester County

Dear Mr. Logan:

On March 24, 1999, I conducted a routine reinspection of this dam with you present. Overall the dam appears to be structurally stable, however we discussed the problem you were having with a beaver population. Please continue to address this problem so that it does not lead to a more serious problem.

I verified the telephone numbers on the Emergency Notification Plan and a copy is enclosed for your use. Should the dam experience difficulty, the agencies listed on the Plan can provide assistance in possibly closing down stream roads or contacting down stream property owners. These agencies should be contacted in case of an emergency occurs.

Provisions in the S. C. Dams and Reservoirs Safety Act require the owner to notify us within 30 days after transferring title or control of his dam to someone else. The notification must include the name and address of the new owner. I am enclosing a blank form for your use in notifying us should control of your dams be transferred.

You will be notified when the next reinspection of this dam is scheduled.

Sincerely

Joe S. Faris, Jr. District Engineer

Enclosures

cc: Richard Yongue, Bur. of Water Fac. Compliance

Phone: 803-285-7461

P.O. Box 100 Fort Lawn, SC 29714

Fax: 803-285-5594

Date 3/24/1999
Dam Logan's Pord Dan: Dan 1439
Representatives of SCDHEC Present: Joe Faris
Representatives of Owner Present: Adron Logan - owner
Others Present:
List of noted deficiencies or items requiring correction/checking:
Continue with rengoval of brush.
Continue control of beaver population to
prevent further damage,
List of previously noted items still uncorrected and dates previously noted:
clear brush from dam slopes
Emergency Action Plan Updated Yes NoX
Detrict Eng.
Signature of Person Completing Form

DHEC 2604 (6/94)



Promotiog and protecting the health of the public and the environment.

November 24, 2008

MR. Warren Norman PO BOX 36518 ROCK HILL, SC 29732

RE: Re-inspection of WARREN NORMAN DAM, D-4547, Lancaster County

Dear Mr. Norman:

On October 30, 2008, I conducted a re-inspection of the above referenced dam. Overall, the dam appears structurally sound. Please continue the maintenance steps that you have completed in past years. The only issue that needs to be addressed involves the area around the spillway. Erosion on the dam and slopes was seen. No ground cover was seen on the surface. This area of the dam needs stabilization. Please address this issue as soon as possible.

A copy of the Emergency Notification Plan is enclosed for your use. Should the dam experience difficulty, the agencies listed on the Plan can provide assistance in possibly closing down stream roads or contacting down stream property owners. These agencies should be contacted in case if an emergency occurs.

Provisions in the S.C. Dams and Reservoirs Safety Act require the owner to notify us within 30 days after transferring title or control of his dam to someone else. The notification must include the name and address of the new owner. I am enclosing a blank form for your use in notifying us should control of your dams be transferred.

You will be notified when the next re-inspection of this dam is scheduled.

Sincerely

District Engineer

Cc: Susan Scott – File Room

Date: 10/30/08	
Dam: D-4547	
Representatives of SCDHEC Present: Greg Harrington	
Others Present:	
Υ	
Listed of noted deficiencies or items requiring correction/checking:	
On October 30, 2008, I conducted a re-inspection of the above referenced dam. Overall, the dam appears structurally sound.	
Please continue the maintenance steps that you have completed	
in past years. The only issue that needs to be addressed	- 0
involves the area around the spillway. Erosion on the dam and	
slopes at the spillway was seen. No ground cover was seen on	
the surface. This area of the dam needs stabilization. Please	
address this issue as soon as possible.	
List of previously noted items still uncorrected and dates previously noted:	
, ————————————————————————————————————	
Emergency Action Plan Updated: X -Yes No	
Cilier gency Action Figure operates. A Tes No	
	Greg Harrington
	DHEC Person Completing Form
DHEC 2604 (10/08)	



Promoting and protecting the health of the public and the environment.

February 9, 2009

Mr. Don Baker PO Box 11676 Rock Hill, SC 29730

RE: Re-inspection of WILLIAM H. BAKER DAM, D 1231, York County

Dear Mr. Don Baker:

On December 17, 2008, I conducted a re-inspection of the above referenced dam. Shrubs and trees should be removed from the downstream slope of the dam. Trees with 6" diameter or more should not be removed. The structure to control the height of water behind the dam did not appear to be working. During my inspection, the level of the water was cresting near the top of the dam. Near the center of the dam, erosion appeared on the top surface of the dam possibly caused by water flowing over the dam. Please address these problems quickly with a time schedule.

An inspection report is enclosed.

A copy of the Emergency Notification Plan is enclosed for your use. Should the dam experience difficulty, the agencies listed on the Plan can provide assistance in possibly closing down stream roads or contacting down stream property owners. These agencies should be contacted in case if an emergency occurs.

Provisions in the S.C. Dams and Reservoirs Safety Act require the owner to notify us within 30 days after transferring title or control of his dam to someone else. The notification must include the name and address of the new owner. I am enclosing a blank form for your use in notifying us should control of your dams be transferred. Since the owner of the dam has changed, please fill out the change in ownership transfer document.

You will be notified when the next re-inspection of this dam is scheduled.

Sincerely.

Greg Harrington

District Engineer Associate email: harringc@dhec.sc.gov

Phone: 803-285-7461

Cc: Susan Scott - File Room

Date: 12/17/08	
Dam: D 1231	
Representatives of SCDHEC Present: Greg Harrington	
Others Present:	
Listed of noted deficiencies or items requiring correction/checking:	
I conducted a re-inspection of the above referenced dam.	
Shrubs and trees should be removed from the downstream slope	
of the dam. Trees with 6" diameter or more should not be	
removed. The structure to control the height of water behind the dam did not appear to be working. During my inspection,	
the level of the water was cresting near the top of the dam.	
Near the center of the dam, erosion appeared on the top surface	
of the dam possibly caused by water flowing over the dam.	
Please address these problems quickly with a time schedule.	
List of previously noted items still uncorrected and dates previously noted:	
Emergency Action Plan Updated: X -Yes No	ï,
	Greg Harrington
	DHEC Person Completing Form
DUED DOC / (ID (DD)	
DHEC 2604 (10/08)	



Promoting and protecting the health of the public and the environment

February 6, 2009

Ms. Simpson 253 OLE SIMPSON PL Catawba, SC 29704

RE: Re-inspection of LOUIS SIMPSON DAMS, D 3651, York County

Dear Ms. Simpson::

On December 3, 2008, Joe Faris conducted a re-inspection of the above referenced dam. Overall, the dam appears structurally sound. Please continue to control vegetation on the upstream and downstream slopes of the dam

An inspection report is enclosed.

A copy of the Emergency Notification Plan is enclosed for your use. Should the dam experience difficulty, the agencies listed on the Plan can provide assistance in possibly closing down stream roads or contacting down stream property owners. These agencies should be contacted in case if an emergency occurs.

Provisions in the S.C. Dams and Reservoirs Safety Act require the owner to notify us within 30 days after transferring title or control of his dam to someone else. The notification must include the name and address of the new owner. I am enclosing a blank form for your use in notifying us should control of your dams be transferred.

You will be notified when the next re-inspection of this dam is scheduled.

Sincerely,

Greg Harrington

District Engineer

Cc: Susan Scott – File Room

Date : 12/3/08	
Dam: D 3651	
Representatives of SCOHEC Present: Joe Faris	
Others Present:	
Listed of noted deficiencies or items requiring correction/checking: Overall, the dam appears structurally sound. Please	
continue to control vegetation on the upstream and downstream slopes of the dam	
List of previously noted items still uncorrected and dates previously noted:	
Emergency Action Plan Updated: X -Yes No	
	Greg Harrington DHEC Person Completing Form
DHEC 2604 (10/08)	
NUCC 7004 (IN/ NO)	



Prayorting and protecting the braith of the public and the environment

October 9, 2008

Mr. John Templeton 13 S CONGRESS ST York, SC 29745

RE: Re-inspection of FISHING CREEK WCD DAM 1, D-3659, York County

Dear Mr. John Templeton:

On October 3, 2008, I conducted a re-inspection of the above referenced dam. The dam appears structurally sound. Please continue maintaining the slopes of the dam to prevent trees and brush from becoming unmanageable.

A copy of the Emergency Notification Plan is enclosed for your use. Should the dam experience difficulty, the agencies listed on the Plan can provide assistance in possibly closing down stream roads or contacting down stream property owners. These agencies should be contacted in case if an emergency occurs.

Provisions in the S.C. Dams and Reservoirs Safety Act require the owner to notify us within 30 days after transferring title or control of his dam to someone else. The notification must include the name and address of the new owner. I am enclosing a blank form for your use in notifying us should control of your dams be transferred.

You will be notified when the next re-inspection of this dam is scheduled.

Sincerely,

Joe S. Faris, Jr. Program Manager

Cc: Susan Scott - File Room

Date: 10/3/08	
Dam: D-3659	
Dani: D-auaa	
Representatives of SCOHEC Present: Joe S. Faris, Jr	
Others Present:	
Listed of noted deficiencies or items requiring correction/checking:	
Continue maintaining the slopes of the dam to prevent trees and brush from becoming unmanageable. All slopes were recently	
cut.	
3a:	
List of previously noted items still uncorrected and dates previously noted: Same	
Pallie	
F A .º FII H. JA. J. V. V N	
Emergency Action Plan Updated: X -Yes No	-
	Joe S. Faris, Jr
	DHEC Person Completing Form
DHEC 2604 (10/08)	
with and I (IN) MA)	



Proporting and protecting the health of the public and the environment.

October 9, 2008

MR. FAULKNER PO BOX 65 SMYRNA, SC 29743

RE: Re-inspection of BELTON POND DAM, D-3660, York County

Dear Mr. FAULKNER:

On October 3, 2008, I conducted a re-inspection of the above referenced dam. Overall the dam appears structurally sound, shrubs should be removed from the slopes of the dam. Trees with 6" diameter or more should not be removed. Please address this issue as soon as possible.

A copy of the Emergency Notification Plan is enclosed for your use. Should the dam experience difficulty, the agencies listed on the Plan can provide assistance in possibly closing down stream roads or contacting down stream property owners. These agencies should be contacted in case if an emergency occurs.

Provisions in the S.C. Dams and Reservoirs Safety Act require the owner to notify us within 30 days after transferring title or control of his dam to someone else. The notification must include the name and address of the new owner. I am enclosing a blank form for your use in notifying us should control of your dams be transferred.

You will be notified when the next re-inspection of this dam is scheduled.

Sincerely,

Joe S. Faris, Jr. Program Manager

Cc: Susan Scott - File Room

Date: 10/3/08	
Date. 107 07 00	· · · · · · · · · · · · · · · · · · ·
Dam: 0-3660	
Nam: n-godn	
Representatives of SCOHEC Present: Joe S. Faris, Jr	
	
Others Present: Mr. Chris Faulkner, Jr Owner	
Listed of nated deficiencies or items requiring correction/checking:	
Shrubs should be removed from the slopes of the dam.	
Trees with 6" diameter or more should not be removed.	
	2
List of previously noted items still uncorrected and dates previously noted:	
Same	
Build	
Emergency Action Plan Updated: X -Yes No	
	Joe S. Faris, Jr
	DHEC Person Completing Form
DHEC 2604 (10/08)	



Propolog and protecting the health of the public and the environment.

November 24, 2008

York NRCS Mr. John Templeton 13 S CONGRESS ST York, SC 29745

RE: Re-inspection of FISHING CREEK WCD DAM 2, D-3662, York County

Dear Mr. John Templeton:

On October 10, 2008, Joe Faris conducted a re-inspection of the above referenced dam. The dam appears structurally sound. Please continue maintaining the slopes of the dam to prevent trees and brush from becoming unmanageable.

A copy of the Emergency Notification Plan is enclosed for your use. Should the dam experience difficulty, the agencies listed on the Plan can provide assistance in possibly closing down stream roads or contacting down stream property owners. These agencies should be contacted in case if an emergency occurs.

Provisions in the S.C. Dams and Reservoirs Safety Act require the owner to notify us within 30 days after transferring title or control of his dam to someone else. The notification must include the name and address of the new owner. I am enclosing a blank form for your use in notifying us should control of your dams be transferred.

You will be notified when the next re-inspection of this dam is scheduled.

Sincerely,

Greg Harrington

Cc: Susan Scott – File Room

Date: 10/10/08	
Dam: D-3662	
Representatives of SCOHEC Present: Joe S. Faris, Jr	
Others Present:	
Listed of noted deficiencies or items requiring correction/checking: On October 10, 2008, Joe Faris conducted a re-inspection of the	
above referenced dam. The dam appears structurally sound.	
Please continue maintaining the slopes of the dam to prevent	
trees and brush from becoming unmanageable.	
List of previously noted items still uncorrected and dates previously noted:	
Emergency Action Plan Updated: X -Yes No	
Lines gency Action Fight opunion. A Tes No	
	Greg Harrington
	DHEC Person Completing Form
DHEC 2604 (10/08)	



Promoting and protecting the health of the public and the environment.

February 6, 2009

MR. GEORGE BURKETT 380 FENCE POST RD ROCK HILL, SC 29730

RE: Re-inspection of BURKETTE LAKE DAM, D 3679, York County

Dear MR. GEORGE BURKETT:

On December 3, 2008, Joe Faris conducted a re-inspection of the above referenced dam. Overall, the dam appears structurally sound. Please continue to control vegetation on the upstream and downstream slopes of the dam

An inspection report is enclosed.

A copy of the Emergency Notification Plan is enclosed for your use. Should the dam experience difficulty, the agencies listed on the Plan can provide assistance in possibly closing down stream roads or contacting down stream property owners. These agencies should be contacted in case if an emergency occurs.

Provisions in the S.C. Dams and Reservoirs Safety Act require the owner to notify us within 30 days after transferring title or control of his dam to someone else. The notification must include the name and address of the new owner. I am enclosing a blank form for your use in notifying us should control of your dams be transferred.

You will be notified when the next re-inspection of this dam is scheduled.

Sincerely,

District Engineer

Cc: Susan Scott - File Room

n , 10/0/00	
Date: 12/3/08	
Dam : D 3679	
Representatives of SCDHEC Present: Joe Faris	
Representatives of addition resent. Due 16/18	
Others Present:	
Listed of noted deficiencies or items requiring correction/checking:	
Overall, the dam appears structurally sound. Please	
continue to control vegetation on the upstream and downstream	
slopes of the dam	
stopes of the dain	
List of previously noted items still uncorrected and dates previously noted:	
,	
Emergency Action Plan Updated: X -Yes No	
The Salah Francisco	,
	5 H
	Greg Harrington
	DHEC Person Completing Form
	*
DHEC 2604 (10/08)	