

PRO DISPOSAL USA (BARNWELL RESOURCES)

CLASS 2 LANDFILL : P1TJ-QJAP-426

Environmental Complaint Evaluation



Inspector: Nadine Mooers

Start Date: 01/07/2025 Completed Date: 01/07/2025

General Complaint Response Section

1a. Start Date of Response 01/07/2025

1b. Time of Response 11:16 AM

GPS Coordinate: 32.472033 -80.645843

1c. End Date of Inspection 01/07/2025

2. General Comments

Complainant reported that Pro Disposal Barnwell on Middle Rd. has an overpowering odor coming from it. Complainant stated that over the past 8-12 months, there is a noxious odor for about one mile along the drive down Middle Road and Brickyard Road coming from Pro Disposal Barnwell Resources. (490 Brickyard Point Road South, Lady's Island). Complainant is concerned that residents are experiencing this strong, extremely unpleasant odor, as they drive on these roads to school and work, and then back home. This area of Lady's Island also includes several neighborhoods where families must endure the odor 24 hours a day. Complainant is concerned that the odor pollutes the air; but could also be contaminating the soil and water. Complainant has written letters to Mr. York Glover (Councilman, District 3) several months ago regarding this issue; however, the complainant never received a reply. Complainant also reached out to Beaufort County offices recently, and complainant was advised to contact SCDES about this issue.

Inspector rode and walked along Middle Road today (1/7/2025) and detected a slight H2S odor at Walnut Hill Development. Inspector turned down Walnut Hill Street and didn't detect odor along entirety of Walnut Hill Street. Inspector then turned left from Walnut Hill Street back onto Middle Road, and made a right turn onto Ardmore, drove along Ardmore and detected a slight H2S odor at Flora Circle. Inspector drove the entirety of Ardmore Avenue and only detected H2S odor at Flora Circle. Inspector stopped at the fence near Better than Ever Road and detected a slight H2S odor (this road is directly adjacent to the landfill). Inspector backed up at "Private Road No Trespassing" sign. Drove down Brickyard Point Road S from Middle Road to Telfair Manor Development at Brickyard Hills Drive and Court, however, didn't detect any H2S odor during entirety of travel on Brickyard Point Road South. Arrived at the landfill scale house at 11:42 am.

Inspector rode in a landfill owned Atlas ATV driven by landfill operator; and an H2S odor was detected at the top of the landfill by the disposal area. During this time it was extremely windy and hard to detect where the odor was originating. Inspector also detected H2S odor on perimeter road of landfill.

3. Approximate Incident Location 32.47482759266707,
-80.64917696194377

4. Complaint Program Area(s) Land & Waste
Management

Complaint Investigation Section

Does the facility/incident meet Hazardous Waste statutory requirements? ☐ Yes ☐ No ☒ NA

Does this facility/incident meet Infectious Waste statutory requirements? ☐ Yes ☐ No ☒ NA

PRO DISPOSAL USA (BARNWELL RESOURCES)

CLASS 2 LANDFILL : P1TJ-QJAP-426

Environmental Complaint Evaluation

Inspector: Nadine Mooers

Start Date: 01/07/2025 Completed Date: 01/07/2025



Complaint Investigation Section

Does this facility/incident meet Solid Waste statutory requirements?

☐ Yes ☒ No ☐ NA

Violation Determined: 1/7/2025
§44-96-10 et seq.

Does this facility/incident meet Underground Storage Tank statutory requirements?

☐ Yes ☐ No ☒ NA

PRO DISPOSAL USA (BARNWELL RESOURCES)
CLASS 2 LANDFILL (P1TJ-QJAP-426)
Violation List



Form	Determined	Description	Sec. #
Environmental Complaint Evaluation	1/7/2025	Reference: §44-96-10 et seq. South Carolina Solid Waste Policy and Management Act of 1991	