

PRO DISPOSAL USA (BARNWELL RESOURCES) CLASS 2 LANDFILL : P1TJ-QJAP-426



Solid Waste - Class 2 Landfill

Inspector Name: Colin Scherer

Start Date: 08/25/2026

Completed Date: 08/25/2026

Solid Waste - Class 2 Landfill

Facility	
Facility Name PRO DISPOSAL USA (BARNWELL RESOURCES) CLASS 2 LANDFILL	
Date of Inspection	8/25/2026
Time of Inspection	10:09 AM
County	Beaufort
Permit #	072410-1201
Inspection Processing	
Reason for Inspection	• Routine • Follow-up
Weather Conditions	Cloudy
Temperature	80s
Rainfall in past week	0-0.5
Weather Condition Description	
Last Inspection	07/22/2026
Inspection Detail	
1. Attendant Present	Yes
2. Required signs posted	Yes
3. Inspection of all incoming loads conducted	Yes
4. Unauthorized waste training conducted and documented	Not Inspected
5. No unauthorized waste present	Yes
6. Access controlled	Yes
7. Adequate entrance all-weather roads	Yes
8. Adequate internal all-weather haul roads	Yes
9. Frequency of cover meets regulatory/ permit requirements	Yes

PRO DISPOSAL USA (BARNWELL RESOURCES) CLASS 2 LANDFILL : P1TJ-QJAP-426



Solid Waste - Class 2 Landfill

Inspector Name: Colin Scherer

Start Date: 08/25/2026

Completed Date: 08/25/2026

Inspection Detail

10. > Six inches of soil (short-term cover) meets regulatory/permit requirements

Yes

Comments:

Facility reported last cover as 8/12/2026.



Photo Taken: 08/25/2026 10:15:00 AM
GPS Latitude: 32.473288
GPS Longitude: -80.648955
GPS Altitude: 9.970000 meters
GPS Orientation: 1 degrees



Photo Taken: 08/25/2026 10:15:00 AM
GPS Latitude: 32.473288
GPS Longitude: -80.648955
GPS Altitude: 9.970000 meters
GPS Orientation: 1 degrees

11. Approved Alternate Monthly Cover (AMC) used

Not Applicable

12. > Six inches of soil (long-term and/or intermediate cover) meets regulatory/permit requirements

Yes

13. Adequate soil quantity available for cover

Yes

14. Working face slope does not exceed 3:1

Yes

PRO DISPOSAL USA (BARNWELL RESOURCES) CLASS 2 LANDFILL : P1TJ-QJAP-426



Solid Waste - Class 2 Landfill

Inspector Name: Colin Scherer

Start Date: 08/25/2026

Completed Date: 08/25/2026

Inspection Detail

15. Waste spread in uniform layers and compacted to smallest practical volume

Yes

16. Working face as small as can efficiently and safely be managed

Yes

Comments:

Working face looks better than last inspection. Continue working on shrinking working face to the smallest manageable size.



Photo Taken: 08/25/2026 10:17:00 AM
GPS Latitude: 32.473288
GPS Longitude: -80.648955
GPS Altitude: 9.970000 meters
GPS Orientation: 1 degrees



Photo Taken: 08/25/2026 10:27:00 AM
GPS Latitude: 32.471000
GPS Longitude: -80.648880
GPS Altitude: 12.300000 meters
GPS Orientation: 1 degrees

PRO DISPOSAL USA (BARNWELL RESOURCES) CLASS 2 LANDFILL : P1TJ-QJAP-426



Solid Waste - Class 2 Landfill

Inspector Name: Colin Scherer

Start Date: 08/25/2026

Completed Date: 08/25/2026

Inspection Detail



Photo Taken: 08/25/2026 10:36:00 AM
GPS Latitude: 32.472452
GPS Longitude: -80.647561
GPS Altitude: 9.200000 meters
GPS Orientation: 1 degrees

17. Asbestos containing material adequately handled

Yes

Comments:

3 loads since last inspection: 7/23, 7/27, and 8/20



Photo Taken: 08/25/2026 10:48:00 AM
GPS Latitude: 32.474730
GPS Longitude: -80.649300
GPS Altitude: 6.070000 meters
GPS Orientation: 1 degrees

18. Dead animals adequately handled

Not Applicable

PRO DISPOSAL USA (BARNWELL RESOURCES) CLASS 2 LANDFILL : P1TJ-QJAP-426



Solid Waste - Class 2 Landfill

Inspector Name: Colin Scherer

Start Date: 08/25/2026

Completed Date: 08/25/2026

Inspection Detail

19. All required equipment operational

Yes

Comments:

Backup compactor down but primary compactor and all other equipment operational.



Photo Taken: 08/25/2026 10:19:00 AM
GPS Latitude: 32.473288
GPS Longitude: -80.648955
GPS Altitude: 9.970000 meters
GPS Orientation: 1 degrees

20. Access to fire equipment and fire fighting services

Yes

21. Disposal area graded to a minimum 1% slope

Yes

22. Adequate condition of ditches/swales

Yes

23. Adequate condition of berms/terraces/downchutes

No

Comments:

Some erosion rills from recent rain, get these repaired. Facility was working on repairing some on the east slope at the time of the inspection.

PRO DISPOSAL USA (BARNWELL RESOURCES) CLASS 2 LANDFILL : P1TJ-QJAP-426



Solid Waste - Class 2 Landfill

Inspector Name: Colin Scherer

Start Date: 08/25/2026

Completed Date: 08/25/2026

Inspection Detail



Photo Taken: 08/25/2026 10:37:00 AM
GPS Latitude: 32.471244
GPS Longitude: -80.647788
GPS Altitude: 8.370000 meters
GPS Orientation: 1 degrees



Photo Taken: 08/25/2026 10:41:00 AM
GPS Latitude: 32.468936
GPS Longitude: -80.649200
GPS Altitude: 5.040000 meters
GPS Orientation: 1 degrees



Photo Taken: 08/25/2026 10:43:00 AM
GPS Latitude: 32.469150
GPS Longitude: -80.649488
GPS Altitude: 5.090000 meters
GPS Orientation: 1 degrees

PRO DISPOSAL USA (BARNWELL RESOURCES) CLASS 2 LANDFILL : P1TJ-QJAP-426



Solid Waste - Class 2 Landfill

Inspector Name: Colin Scherer

Start Date: 08/25/2026

Completed Date: 08/25/2026

Inspection Detail	
24. Adequate condition of sedimentation ponds	Yes
25. Control of Dust	Yes
26. Control of Litter	Yes
Comments: Litter fencing present.	
 Aug 25, 2026 at 10:34:00 AM Barnwell SC 29907 United States Lady's Island Photo Taken: 08/25/2026 10:34:00 AM GPS Latitude: 32.471788 GPS Longitude: -80.649352 GPS Altitude: 21.310000 meters GPS Orientation: 1 degrees	
27. Control of Odors	Yes
Comments: No detectable H2S odor off site.	
28. Control of Vectors	Yes
29. Control of Fires/Open Burning	Yes
30. Scales installed and functioning properly	Yes
31. Scales calibrated adequately	Yes

PRO DISPOSAL USA (BARNWELL RESOURCES) CLASS 2 LANDFILL : P1TJ-QJAP-426



Solid Waste - Class 2 Landfill

Inspector Name: Colin Scherer

Start Date: 08/25/2026

Completed Date: 08/25/2026

Inspection Detail

31a. Last date of calibration

3/23/2026



Photo Taken: 08/25/2026 10:06:00 AM
GPS Latitude: 32.474747
GPS Longitude: -80.649361
GPS Altitude: 4.000000 meters
GPS Orientation: 6 degrees

32. Monitoring well pads are free of sediment buildup and standing water

Not Inspected

33. Monitoring wells pads are free of cracks

Not Inspected

34. Monitoring wells are labeled

Not Inspected

35. Monitoring wells are locked

Not Inspected

36. Operating in accordance with approved plans

Yes

37. Approved engineering drawings available

Not Inspected

38. Approved operational plan available

Not Inspected

39. Approved stabilization/landscaping plan available

Not Inspected

40. Approved contingency plan available

Not Inspected

41. Approved groundwater monitoring plan available

Not Inspected

42. Approved closure/post-closure plan available

Not Inspected

43. Required records maintained

Not Inspected

PRO DISPOSAL USA (BARNWELL RESOURCES) CLASS 2 LANDFILL : P1TJ-QJAP-426



Solid Waste - Class 2 Landfill

Inspector Name: Colin Scherer

Start Date: 08/25/2026

Completed Date: 08/25/2026

Corrective Action

1. Corrective Action Due Date

9/25/2026

Comments:

Repair washouts in slopes.

PRO DISPOSAL USA (BARNWELL RESOURCES) CLASS 2 LANDFILL : P1TJ-QJAP-426



Solid Waste - Class 2 Landfill

Inspector Name: Colin Scherer

Start Date: 08/25/2026

Completed Date: 08/25/2026

Additional Comments

Record any additional information regarding the current activities at the site that has not already been captured in the previous questions

Facility's own odor logs checked.



Photo Taken: 08/25/2026 10:07:00 AM
GPS Latitude: 32.474747
GPS Longitude: -80.649361
GPS Altitude: 4.000000 meters
GPS Orientation: 1 degrees




Photo Taken: 08/25/2026 10:07:00 AM
GPS Latitude: 32.474747
GPS Longitude: -80.649361
GPS Altitude: 4.000000 meters
GPS Orientation: 1 degrees

PRO DISPOSAL USA (BARNWELL RESOURCES) CLASS 2 LANDFILL : P1TJ-QJAP-426



Solid Waste - Class 2 Landfill

Inspector Name: Colin Scherer

Start Date: 08/25/2026

Completed Date: 08/25/2026

Additional Comments




Photo Taken: 08/25/2026 10:07:00 AM
GPS Latitude: 32.474747
GPS Longitude: -80.649361
GPS Altitude: 4.000000 meters
GPS Orientation: 1 degrees




Photo Taken: 08/25/2026 10:07:00 AM
GPS Latitude: 32.474747
GPS Longitude: -80.649361
GPS Altitude: 4.000000 meters
GPS Orientation: 1 degrees



Photo Taken: 08/25/2026 10:07:00 AM
GPS Latitude: 32.474747
GPS Longitude: -80.649361
GPS Altitude: 4.000000 meters
GPS Orientation: 1 degrees

PRO DISPOSAL USA (BARNWELL RESOURCES) CLASS 2 LANDFILL : P1TJ-QJAP-426



Solid Waste - Class 2 Landfill

Inspector Name: Colin Scherer

Start Date: 08/25/2026

Completed Date: 08/25/2026

Signature

Name of those present during inspection

Chad Stanley, Colin Scherer, Rohan Preis

1. Facility Representative

A handwritten signature in black ink, appearing to read "Chad Stanley".

1a. Facility Representative Name

Chad Stanley

2. SCDES Inspector

A handwritten signature in black ink, appearing to be a stylized "C. Scherer".

2a. SCDES Inspector Name

Colin T. Scherer