

PRO DISPOSAL USA (BARNWELL RESOURCES) CLASS 2 LANDFILL : P1TJ-QJAP-426



Solid Waste - Class 2 Landfill : SW_CLS2_LF

Solid Waste - Class 2 Landfill	
Facility	
Facility Name PRO DISPOSAL USA (BARNWELL RESOURCES) CLASS 2 LANDFILL	
Date of Inspection	7/22/2026
Time of Inspection	10:35 AM
County	Beaufort
Permit #	072410-1201
Inspection Processing	
Reason for Inspection	Routine,Follow-up
Weather Conditions	Cloudy
Temperature	80s
Rainfall in past week	0-0.5
Weather Condition Description	
Last Inspection	06/15/2026
Inspection Detail	
1. Attendant Present	Yes
2. Required signs posted	Yes
3. Inspection of all incoming loads conducted	Yes
4. Unauthorized waste training conducted and documented	Not Inspected
5. No unauthorized waste present	Yes
6. Access controlled	Yes
7. Adequate entrance all-weather roads	Yes
8. Adequate internal all-weather haul roads	Yes

PRO DISPOSAL USA (BARNWELL RESOURCES) CLASS 2 LANDFILL : P1TJ-QJAP-426



Solid Waste - Class 2 Landfill : SW_CLS2_LF

Inspection Detail

9. Frequency of cover meets regulatory/ permit requirements No

Comments:

A portion of last month's working face adjacent to internal road has been covered, but did not meet the 30 day requirement for all exposed waste.



Photo Taken: 7/22/2026 10:39:00 AM
GPS Latitude: 32.473133
GPS Longitude: -80.649122
GPS Altitude: 9.280000 meters
GPS Orientation: 1 degrees



Photo Taken: 7/22/2026 10:44:00 AM
GPS Latitude: 32.471275
GPS Longitude: -80.648705
GPS Altitude: 17.380000 meters
GPS Orientation: 1 degrees

10. > Six inches of soil (short-term cover) meets regulatory/permit requirements Yes

11. Approved Alternate Monthly Cover (AMC) used Not Applicable

12. > Six inches of soil (long-term and/or intermediate cover) meets regulatory/permit requirements Yes

13. Adequate soil quantity available for cover Yes

14. Working face slope does not exceed 3:1 Yes

PRO DISPOSAL USA (BARNWELL RESOURCES) CLASS 2 LANDFILL : P1TJ-QJAP-426



Solid Waste - Class 2 Landfill : SW_CLS2_LF

Inspection Detail

15. Waste spread in uniform layers and compacted to smallest practical volume

Yes

Comments:

Compactor is back online, compaction looks a lot better than last month's.

16. Working face as small as can efficiently and safely be managed

No

Comments:

Working face a little smaller than last month's but still large.



Photo Taken: 7/22/2026 10:39:00 AM
GPS Latitude: 32.473133
GPS Longitude: -80.649122
GPS Altitude: 9.280000 meters
GPS Orientation: 1 degrees



Photo Taken: 7/22/2026 10:39:00 AM
GPS Latitude: 32.474827
GPS Longitude: -80.649222
GPS Altitude: 5.800000 meters
GPS Orientation: 1 degrees

PRO DISPOSAL USA (BARNWELL RESOURCES) CLASS 2 LANDFILL : P1TJ-QJAP-426



Solid Waste - Class 2 Landfill : SW_CLS2_LF

Inspection Detail



Photo Taken: 7/22/2026 10:44:00 AM
GPS Latitude: 32.471275
GPS Longitude: -80.648705
GPS Altitude: 17.380000 meters
GPS Orientation: 1 degrees

17. Asbestos containing material adequately handled	Not Applicable
18. Dead animals adequately handled	Not Applicable
19. All required equipment operational	Yes
20. Access to fire equipment and fire fighting services	Yes
21. Disposal area graded to a minimum 1% slope	Yes
22. Adequate condition of ditches/swales	Yes

PRO DISPOSAL USA (BARNWELL RESOURCES) CLASS 2 LANDFILL : P1TJ-QJAP-426



Solid Waste - Class 2 Landfill : SW_CLS2_LF

Inspection Detail

23. Adequate condition of berms/terraces/downchutes

Yes

Comments:

Small berm of dirt has been added along eastern edge of top of landfill to control stormwater. No erosion rills noted on the eastern slopes. Grass growth looks better.



7/22/2026 at 10:42:08 AM
Barnwell SC 29907
United States
Lady's Island

Photo Taken: 7/22/2026 10:42:00 AM
GPS Latitude: 32.471072
GPS Longitude: -80.648850
GPS Altitude: 11.750000 meters
GPS Orientation: 1 degrees



7/22/2026 at 10:43:07 AM
Barnwell SC 29907
United States
Lady's Island

Photo Taken: 7/22/2026 10:43:00 AM
GPS Latitude: 32.471072
GPS Longitude: -80.648850
GPS Altitude: 11.750000 meters
GPS Orientation: 1 degrees

24. Adequate condition of sedimentation ponds

Yes

25. Control of Dust

Yes

26. Control of Litter

Yes

PRO DISPOSAL USA (BARNWELL RESOURCES) CLASS 2 LANDFILL : P1TJ-QJAP-426



Solid Waste - Class 2 Landfill : SW_CLS2_LF

Inspection Detail	
27. Control of Odors	Yes
<i>Comments:</i> No H2S smell detected off site on Middle Rd. today despite windy conditions.	
28. Control of Vectors	Yes
29. Control of Fires/Open Burning	Yes
30. Scales installed and functioning properly	Yes
31. Scales calibrated adequately	Not Inspected
32. Monitoring well pads are free of sediment buildup and standing water	Not Inspected
33. Monitoring wells pads are free of cracks	Not Inspected
34. Monitoring wells are labeled	Not Inspected
35. Monitoring wells are locked	Not Inspected
36. Operating in accordance with approved plans	Yes
37. Approved engineering drawings available	Not Inspected
38. Approved operational plan available	Not Inspected
39. Approved stabilization/landscaping plan available	Not Inspected
40. Approved contingency plan available	Not Inspected
41. Approved groundwater monitoring plan available	Not Inspected
42. Approved closure/post-closure plan available	Not Inspected
43. Required records maintained	Not Inspected
Corrective Action	
1. Corrective Action Due Date	8/22/2026
<i>Comments:</i> Cover all exposed waste within 30 days per regulatory requirement and maintain a smaller working face size.	

PRO DISPOSAL USA (BARNWELL RESOURCES) CLASS 2 LANDFILL : P1TJ-QJAP-426



Solid Waste - Class 2 Landfill : SW_CLS2_LF

Additional Comments

Record any additional information regarding the current activities at the site that has not already been captured in the previous questions

Operator informed me soil samples have been taken from eastern slope areas where grass has not been growing to get the right type of seed identified for future growth.




Photo Taken: 7/22/2026 11:03:00 AM
GPS Latitude: 32.474755
GPS Longitude: -80.649130
GPS Altitude: 6.530000 meters
GPS Orientation: 1 degrees




Photo Taken: 7/22/2026 11:03:00 AM
GPS Latitude: 32.474755
GPS Longitude: -80.649130
GPS Altitude: 6.530000 meters
GPS Orientation: 1 degrees

Signature

Name of those present during inspection

Maci Dean, Colin Scherer

PRO DISPOSAL USA (BARNWELL RESOURCES) CLASS 2 LANDFILL : P1TJ-QJAP-426



Solid Waste - Class 2 Landfill : SW_CLS2_LF

Signature

1. Facility Representative

A handwritten signature in black ink, appearing to read "Maci Dean", written over a light gray background.

1a. Facility Representative Name

Maci Dean

2. SCDES Inspector

A handwritten signature in black ink, appearing to read "Colin T. Scherer", written over a light gray background.

2a. SCDES Inspector Name

Colin T. Scherer