

PRO DISPOSAL USA (BARNWELL RESOURCES)
CLASS 2 LANDFILL : P1TJ-QJAP-426



Solid Waste - Class 2 Landfill

Inspector: Amanda Neyman

Start Date: 04/28/2025 Completed Date: 05/01/2025

Facility	
<i>Facility Name</i>	PRO DISPOSAL USA (BARNWELL RESOURCES) CLASS 2 LANDFILL
<i>Date of Inspection</i>	04/29/2025
<i>Time of Inspection</i>	1:15 PM
<i>County</i>	Beaufort
<i>Permit #</i>	072410-1201
Inspection Processing	
<i>Reason for Inspection</i>	Routine
<i>Weather Conditions</i>	Sunny
<i>Temperature</i>	70s
<i>Rainfall in past week</i>	0-0.5
<i>Weather Condition Description</i>	
<i>Last Inspection</i>	03/31/2025
Inspection Detail	
<i>1. Attendant Present</i>	Yes
<i>2. Required signs posted</i>	Yes
<i>3. Inspection of all incoming loads conducted</i>	Yes
<i>4. Unauthorized waste training conducted and documented</i>	Yes
<i>5. No unauthorized waste present</i>	Yes
<i>6. Access controlled</i>	Yes
<i>7. Adequate entrance all-weather roads</i>	Yes
<i>8. Adequate internal all-weather haul roads</i>	Yes
<i>9. Frequency of cover meets regulatory/ permit requirements</i>	Yes
<i>10. > Six inches of soil (short-term cover) meets regulatory/permit requirements</i>	Yes
<i>11. Approved Alternate Monthly Cover (AMC) used</i>	No

PRO DISPOSAL USA (BARNWELL RESOURCES)
CLASS 2 LANDFILL : P1TJ-QJAP-426



Solid Waste - Class 2 Landfill

Inspector: Amanda Neyman

Start Date: 04/28/2025 Completed Date: 05/01/2025

Inspection Detail	
12. > Six inches of soil (long-term and/or intermediate cover) meets regulatory/permit requirements	Yes
13. Adequate soil quantity available for cover	Yes
14. Working face slope does not exceed 3:1	Yes
15. Waste spread in uniform layers and compacted to smallest practical volume	Yes
16. Working face as small as can efficiently and safely be managed	Yes
17. Asbestos containing material adequately handled	Not Inspected
18. Dead animals adequately handled	Not Inspected
19. All required equipment operational	Yes
20. Access to fire equipment and fire fighting services	Yes
21. Disposal area graded to a minimum 1% slope	Yes
22. Adequate condition of ditches/swales	Yes
23. Adequate condition of berms/terraces/downchutes	Yes
24. Adequate condition of sedimentation ponds	Yes
25. Control of Dust	Yes
Roads could use some watering down.	
26. Control of Litter	Yes
27. Control of Odors	Yes
28. Control of Vectors	Yes
29. Control of Fires/Open Burning	Yes
30. Scales installed and functioning properly	Yes
31. Scales calibrated adequately	Not Inspected
32. Monitoring well pads are free of sediment buildup and standing water	Not Inspected
33. Monitoring wells pads are free of cracks	Not Inspected
34. Monitoring wells are labeled	Not Inspected

PRO DISPOSAL USA (BARNWELL RESOURCES)
CLASS 2 LANDFILL : P1TJ-QJAP-426



Solid Waste - Class 2 Landfill

Inspector: Amanda Neyman

Start Date: 04/28/2025 Completed Date: 05/01/2025

Inspection Detail

<i>35. Monitoring wells are locked</i>	Not Inspected
<i>36. Operating in accordance with approved plans</i>	Yes
<i>37. Approved engineering drawings available</i>	Not Inspected
<i>38. Approved operational plan available</i>	Not Inspected
<i>39. Approved stabilization/landscaping plan available</i>	Not Inspected
<i>40. Approved contingency plan available</i>	Not Inspected
<i>41. Approved groundwater monitoring plan available</i>	Not Inspected
<i>42. Approved closure/post-closure plan available</i>	Not Inspected
<i>43. Required records maintained</i>	Not Inspected

Corrective Action

<i>1. Corrective Action Due Date</i>

PRO DISPOSAL USA (BARNWELL RESOURCES)

CLASS 2 LANDFILL : P1TJ-QJAP-426

Solid Waste - Class 2 Landfill

Inspector: Amanda Neyman

Start Date: 04/28/2025 Completed Date: 05/01/2025



Additional Comments

Record any additional information regarding the current activities at the site that has not already been captured in the previous questions



Photo Taken: 4/29/2025 1:21:00 PM
GPS Latitude: 32.472745
GPS Longitude: 80.648742



Photo Taken: 4/29/2025 1:21:00 PM
GPS Latitude: 32.471347
GPS Longitude: 80.649017

Signature

Name of those present during inspection

Amanda Neyman, Maci Dean

1. Facility Representative

1a. Facility Representative Name

Maci Dean

PRO DISPOSAL USA (BARNWELL RESOURCES)

CLASS 2 LANDFILL : P1TJ-QJAP-426

Solid Waste - Class 2 Landfill

Inspector: Amanda Neyman

Start Date: 04/28/2025 Completed Date: 05/01/2025



Signature

2. SCDES Inspector

A handwritten signature in black ink, appearing to read "Amanda A. Neyman", written over a light gray background.

2a. SCDES Inspector Name

Amanda A. Neyman

PRO DISPOSAL USA (BARNWELL RESOURCES)
CLASS 2 LANDFILL (P1TJ-QJAP-426)
Violation List

No Violations Found