

# PRO DISPOSAL USA (BARNWELL RESOURCES) CLASS 2 LANDFILL



P1TJ-QJAP-426

Inspector: Colin Sherer

Start Date: 01/21/2026      Completed Date: 01/21/2026

<b>Solid Waste - Class 2 Landfill</b>	
<b>Facility</b>	
<b>Facility Name</b>	PRO DISPOSAL USA (BARNWELL RESOURCES) CLASS 2 LANDFILL
<b>Date of Inspection</b>	1/21/2026
<b>Time of Inspection</b>	9:21 AM
<b>County</b>	Beaufort
<b>Permit #</b>	072410-1201
<b>Inspection Processing</b>	
<b>Reason for Inspection</b>	Routine
<b>Weather Conditions</b>	Sunny
<b>Temperature</b>	40s
<b>Rainfall in past week</b>	0.5-1
<b>Weather Condition Description</b>	
<b>Last Inspection</b>	01/09/2026
<b>Inspection Detail</b>	
<b>1. Attendant Present</b>	Yes
<b>2. Required signs posted</b>	Yes
<b>3. Inspection of all incoming loads conducted</b>	Yes
<b>4. Unauthorized waste training conducted and documented</b>	Not Inspected
<b>5. No unauthorized waste present</b>	Yes
<b>6. Access controlled</b>	Yes
<b>7. Adequate entrance all-weather roads</b>	Yes
<b>8. Adequate internal all-weather haul roads</b>	Yes

# PRO DISPOSAL USA (BARNWELL RESOURCES) CLASS 2 LANDFILL



P1TJ-QJAP-426

Inspector: Colin Sherer

Start Date: 01/21/2026      Completed Date: 01/21/2026

Inspection Detail	
<b>9. Frequency of cover meets regulatory/ permit requirements</b>	Yes
<i>Comments:</i> Covering as they work, has been covered since last inspection 1/09/26.	
<b>10. &gt; Six inches of soil (short-term cover) meets regulatory/permit requirements</b>	Yes
<b>11. Approved Alternate Monthly Cover (AMC) used</b>	Not Applicable
<i>Comments:</i> Tarp is on order for covering turn-around areas of working face to limit smell.	
<b>12. &gt; Six inches of soil (long-term and/or intermediate cover) meets regulatory/permit requirements</b>	Yes
<b>13. Adequate soil quantity available for cover</b>	Yes
<b>14. Working face slope does not exceed 3:1</b>	Yes

# PRO DISPOSAL USA (BARNWELL RESOURCES) CLASS 2 LANDFILL



P1TJ-QJAP-426

Inspector: Colin Sherer

Start Date: 01/21/2026      Completed Date: 01/21/2026

## Inspection Detail

**15. Waste spread in uniform layers and compacted to smallest practical volume** Yes

	<p>Photo Taken: 1/21/2026 2:29:00 PM          GPS Latitude: 32.471450000000004          GPS Longitude: -80.6494138888889          GPS Altitude: 18.48 meters          GPS Orientation: 1 degrees</p>
	<p>Photo Taken: 1/21/2026 2:32:00 PM          GPS Latitude: 32.47123055555556          GPS Longitude: -80.6494138888889          GPS Altitude: 15.88 meters          GPS Orientation: 1 degrees</p>

**16. Working face as small as can efficiently and safely be managed** Yes

**17. Asbestos containing material adequately handled** Not Applicable

**18. Dead animals adequately handled** Not Applicable

**19. All required equipment operational** Yes

**20. Access to fire equipment and fire fighting services** Yes

**21. Disposal area graded to a minimum 1% slope** Yes

# PRO DISPOSAL USA (BARNWELL RESOURCES) CLASS 2 LANDFILL



P1TJ-QJAP-426

Inspector: Colin Sherer

Start Date: 01/21/2026      Completed Date: 01/21/2026

<b>Inspection Detail</b>	
<b>22. Adequate condition of ditches/swales</b>	Yes
<b>23. Adequate condition of berms/terraces/downchutes</b>	Yes
<b>24. Adequate condition of sedimentation ponds</b>	Yes
<b>25. Control of Dust</b>	Yes
<b>26. Control of Litter</b>	Yes
<i>Comments:</i> Some wind-blown litter, make sure it is under control.	
<b>27. Control of Odors</b>	No
<i>Comments:</i> Smell present on top deck and around base to the south. Did not smell the odor driving in on Middle Rd.	
<b>28. Control of Vectors</b>	Yes
<b>29. Control of Fires/Open Burning</b>	Yes
<b>30. Scales installed and functioning properly</b>	Yes
<b>31. Scales calibrated adequately</b>	Not Inspected
<b>32. Monitoring well pads are free of sediment buildup and standing water</b>	Not Inspected
<b>33. Monitoring wells pads are free of cracks</b>	Not Inspected
<b>34. Monitoring wells are labeled</b>	Not Inspected
<b>35. Monitoring wells are locked</b>	Not Inspected
<b>36. Operating in accordance with approved plans</b>	Yes
<b>37. Approved engineering drawings available</b>	Not Inspected
<b>38. Approved operational plan available</b>	Not Inspected
<b>39. Approved stabilization/landscaping plan available</b>	Not Inspected
<b>40. Approved contingency plan available</b>	Not Inspected

# PRO DISPOSAL USA (BARNWELL RESOURCES) CLASS 2 LANDFILL



P1TJ-QJAP-426

Inspector: Colin Sherer

Start Date: 01/21/2026      Completed Date: 01/21/2026

<b>Inspection Detail</b>	
<b>41. Approved groundwater monitoring plan available</b>	Not Inspected
<b>42. Approved closure/post-closure plan available</b>	Not Inspected
<b>43. Required records maintained</b>	Not Inspected
<b>Corrective Action</b>	
<b>1. Corrective Action Due Date</b>	

# PRO DISPOSAL USA (BARNWELL RESOURCES) CLASS 2 LANDFILL



P1TJ-QJAP-426

Inspector: Colin Sherer

Start Date: 01/21/2026      Completed Date: 01/21/2026

## Additional Comments

**Record any additional information regarding the current activities at the site that has not already been captured in the previous questions**

Working face is moving eastward and covering as they go. Long term plan is to receive waste on top shelf until final elevation is reached, then to apply final cap/cover. In March/April the facility will apply lime to east slope and hydro seed with spring/summer grass to control erosion. Gas sampling wells have been added to top deck to determine gas composition for potential gas management systems. Facility continues to collect their own odor assessment data.



Photo Taken: 1/21/2026 2:33:00 PM  
GPS Latitude: 32.470908333333334  
GPS Longitude: -80.6493138888889  
GPS Altitude: 19.25 meters  
GPS Orientation: 1 degrees



Photo Taken: 1/21/2026 2:34:00 PM  
GPS Latitude: 32.470797222222224  
GPS Longitude: -80.64864444444446  
GPS Altitude: 10.93 meters  
GPS Orientation: 1 degrees



# PRO DISPOSAL USA (BARNWELL RESOURCES) CLASS 2 LANDFILL



P1TJ-QJAP-426

Inspector: Colin Scherer

Start Date: 01/21/2026      Completed Date: 01/21/2026

## Additional Comments




Photo Taken: 1/21/2026 3:04:00 PM  
 GPS Latitude: 32.474900000000005  
 GPS Longitude: -80.64922222222224  
 GPS Altitude: 16.73 meters  
 GPS Orientation: 1 degrees




Photo Taken: 1/21/2026 3:04:00 PM  
 GPS Latitude: 32.474900000000005  
 GPS Longitude: -80.64922222222224  
 GPS Altitude: 16.73 meters  
 GPS Orientation: 1 degrees

## Signature

**Name of those present during inspection**

Chad Stanley, Colin Scherer, Ashley Esposito

**1. Facility Representative**

**1a. Facility Representative Name**

Chad Stanley

**2. SCDES Inspector**

**2a. SCDES Inspector Name**

Colin T. Scherer

PRO DISPOSAL USA (BARNWELL RESOURCES)  
CLASS 2 LANDFILL (P1TJ-QJAP-426)  
Violation List

No Violations Found