PRO DISPOSAL USA (BARNWELL RESOURCES) CLASS 2 LANDFILL : P1TJ-QJAP-426



Solid Waste - Class 2 Landfill Inspector: Nadine Mooers

Start Date: 06/10/2025 Completed Date: 06/10/2025

Start Date: 06/10/2025	
Facility	
Facility Name	PRO DISPOSAL USA (BARNWELL RESOURCES) CLASS 2 LANDFILL
Date of Inspection	06/10/2025
Time of Inspection	12:03 PM
County	Beaufort
Permit #	072410-1201
Inspection Processing	
Reason for Inspection	Routine
Weather Conditions	Raining
Temperature	80s
Rainfall in past week	2.5-3
Weather Condition Description	
Last Inspection	05/23/2025
Inspection Detail	
1. Attendant Present	Yes
2. Required signs posted	Yes
3. Inspection of all incoming loads conducted	Yes
4. Unauthorized waste training conducted and documented	Yes
5. No unauthorized waste present	Yes
6. Access controlled	Yes
7. Adequate entrance all-weather roads	Yes
8. Adequate internal all-weather haul roads	Yes
9. Frequency of cover meets regulatory/ permit requirements	Yes
10. > Six inches of soil (short-term cover) meets regulatory/permit requirements	Yes
11. Approved Alternate Monthly Cover (AMC) used	No

PRO DISPOSAL USA (BARNWELL RESOURCES) CLASS 2 LANDFILL : P1TJ-QJAP-426



Solid Waste - Class 2 Landfill Inspector: Nadine Mooers

Start Date: 06/10/2025 Completed Date: 06/10/2025

.drt Date. 00/10/2025 Completed Date. 00/10/2025	
nspection Detail	
12. > Six inches of soil (long-term and/or intermediate cover) meets regulatory/permit requirements	Yes
13. Adequate soil quantity available for cover	Yes
14. Working face slope does not exceed 3:1	Yes
15. Waste spread in uniform layers and compacted to smallest practical volume	Yes
16. Working face as small as can efficiently and safely be managed	Yes
17. Asbestos containing material adequately handled	Yes
18. Dead animals adequately handled	Not Applicable
19. All required equipment operational	Yes
20. Access to fire equipment and fire fighting services	Yes
21. Disposal area graded to a minimum 1% slope	Yes
22. Adequate condition of ditches/swales	No
Currently cleaning out the ditches.	
23. Adequate condition of berms/terraces/downchutes	Yes
Some washouts were observed on the side slopes. Operator is currently re GPS Coordinate: 32.471857 -80.650382	epairing rills and washouts
24. Adequate condition of sedimentation ponds	Yes
25. Control of Dust	Yes
26. Control of Litter	Yes
27. Control of Odors	No
Slight odor detected on Middle Road.	
28. Control of Vectors	Yes
29. Control of Fires/Open Burning	Yes
30. Scales installed and functioning properly	Yes
31. Scales calibrated adequately	Yes
51. Scares camprated adequatery	

PRO DISPOSAL USA (BARNWELL RESOURCES) CLASS 2 LANDFILL: P1TJ-QJAP-426



Solid Waste - Class 2 Landfill Inspector: Nadine Mooers

Start Date: 06/10/2025 Completed Date: 06/10/2025

Start Date: 06/10/2025	
Inspection Detail	
32. Monitoring well pads are free of sediment buildup and standing water	r Not Inspected
33. Monitoring wells pads are free of cracks	Not Inspected
34. Monitoring wells are labeled	Not Inspected
35. Monitoring wells are locked	Not Inspected
36. Operating in accordance with approved plans	Yes
37. Approved engineering drawings available	Not Inspected
38. Approved operational plan available	Not Inspected
39. Approved stabilization/landscaping plan available	Not Inspected
40. Approved contingency plan available	Not Inspected
41. Approved groundwater monitoring plan available	Not Inspected
42. Approved closure/post-closure plan available	Not Inspected
43. Required records maintained	Yes
Corrective Action	
1. Corrective Action Due Date	

Additional Comments

Record any additional information regarding the current activities at the site that has not already been captured in the previous questions

Signature

Name of those present during inspection Nadine Mooers and Maci Dean

1. Facility Representative

1a. Facility Representative Name Maci Dean

PRO DISPOSAL USA (BARNWELL RESOURCES) CLASS 2 LANDFILL: P1TJ-QJAP-426



Solid Waste - Class 2 Landfill Inspector: Nadine Mooers

Signature

2. SCDES Inspector

2a. SCDES Inspector Name

Nadine M. Mooers

PRO DISPOSAL USA (BARNWELL RESOURCES) CLASS 2 LANDFILL (P1TJ-QJAP-426) Violation List

No Violations Found