

Westinghouse Fuel Fabrication Facility July 25, 2019

Hopkins, South Carolina

South Carolina Department of Health and Environmental Control Healthy People. Healthy Communities.

Overview

- Site History
- Consent Agreement
- Current Investigations

What Does Westinghouse Do?




- Operates a 550,000 square foot facility on 1,156 acres
- Began operations in 1969
- Manufactures Nuclear Fuel Rods
- Not a Nuclear Power Plant



Hydrogeology Setting and Overview






















Groundwater Flow Direction








Westinghouse Plant



FIGURE 4-3 EAST-WEST HYDROGEOLOGIC CROSS-SECTION D-D' OF THE TERRACE HYDROGEOLOGIC UNIT SOUTH OF THE PROCESS AREA







Regulatory Roles

US Nuclear Regulatory Commission (NRC)

- License and Regulate the use of radiologic materials
- Emergency Plans
- Conducts Inspections

SC DHEC

- Assure proper investigation and cleanup of hazardous materials released into the environment under the Consent Agreement
- Air and Water Discharge Permits



Environmental History

- 1980s First Groundwater Assessment Due to Fish Kill in Gator Pond
- Monitoring Well Network Established
- Determined the Wastewater Lagoons were leaking Nitrates and Fluoride to the Groundwater
- Groundwater Monitoring has Continued Since the 1980s to the present

- In 1995 Solvent Chemical Contamination was Discovered in Groundwater
- Additional Investigation (more monitoring wells) Targeted the Solvent Contamination
- 1996-2011 Groundwater Treatment to Reduce the Solvents in Groundwater
- 2011 System Turned Off as Solvent Concentrations had Stopped Declining



Known Contaminants In Groundwater

- Nitrate
- Fluoride
- Ammonia
- Solvents-

Tetrachloroethene (PCE) & Trichloroethene (TCE)

- Technetium-99
- Uranium

Nitrate Extent In Groundwater Eastern Ditch Western Ditch SED-11 SW-11 W-88 W-89 SW-15 SED-15 L-12 Middle Ditch Building W-90 W-91 L-18 -SW-17 SED-17 SW-16 SW-23 SED-24 SW-20 SED 20 L-10 W-97 - L-1 W-96 L-8 W-05 📁 ● L-5

Solvent Extent in Groundwater SW-12 Eastern Ditch. Western Ditch SED-11 SW-11 W-88 W-89 SW-15 SED-15 Middle Ditch Plant Building W-90 W-91 SW-17 SED-17 SW-16 SED-14 SW-23 L-2 W-27 W-92 SED-21 SW-21 W-94 - L-1 W-96 ● L-8 SED-22 W-05 🧭 SW-22 ● L-5



Consent Agreement



Executed February 26, 2019

- Establishes a Communication Protocol
- Integrates Investigation of all Past and Current Releases
- Response Mechanism for any Future Release
- Requires Evaluation of Cleanup Alternatives
- Remedial Design
- Remedial Action



Consent Agreement

Why?

A need to coordinate the individual contaminant release incidents into one broad, comprehensive agreement.



Consent Agreement

Over the past year, several issues have been reported needing investigation and a path to closure.

- Wastewater line leaks from 2008 and 2011 were reported in early 2018
- Hydrofluoric Acid Station leak through floor discovered and reported summer of 2018

No formal process was in place to investigate and resolve these issues...thus the need for the Consent Agreement

Consent Agreement


Now there is a comprehensive and consistent process in place to deal with all current and future releases to the environment


Current Investigation




Remedial Investigation Work Plan - Approved June 19, 2019

- 29 new monitoring wells
- 56 Soil Samples
- 13 Surface Water Samples
- 18 Sediment Samples
- Sampling of all Groundwater Monitoring Wells








Update


- HF Spiking Station
- Private Well Sampling
- Sea Land Containers



HF Spiking Station

- A 16 by 12 ft area inside the plant building
- All soil beneath the station has been removed to a depth of 12 feet and filled back in with concrete.
- No evidence that groundwater was effected
- Work is complete










Private Well Sampling Summer 2018

- DHEC Sampled 14 Private Wells
- Richland County Sampled 62 Private Wells

None of the wells sampled showed any detection of any contaminant known in the groundwater at Westinghouse





Sea Land Containers

- Inspection by Westinghouse on 5/31/19 found one with hole in its roof
- Some drums inside were in poor condition. They are filled with materials containing Uranium for recovery – rags mops, etc.
- Inspected all other containers





Sea Land Containers

- As the Sea Land containers are emptied, the soil beneath them will be sampled.
- This Area is part of the Southern Storage Area included for investigation under the Consent Agreement.





Drum Incident July 12, 2019



Pictured at left is the drum containing the items that self-ignited. Material on the floor was removed for inspection as part of the analysis of the incident.



CONTACT US

www.scdhec.gov/Westinghouse

Stay Connected









